Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103	_
Revised 1-1-89	•

(This space for State Use)	District Office		on our Department	Revised 1-1-89	
Sample S		P.O. Box 2088		WELL API NO.	
S. Indicate Type of Lase No.	DISTRICT II			I I	
CON NOTICE OF INTENTION TO: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data SUBSEQUENT REPORT OF: Comment of Notice, Report, or Other Data Subsequent Proposed or Other Data Subsequ	-				
Type of Well: Well Compared Type of Well: Type of Type		M 87410		6. State Oil & Gas Lease No.	
1. Type of Well: Collect Collec	(DO NOT USE THIS FOR	M FOR PROPOSALS TO DRILL OR TO DEEPEN (ENT RESERVOIR. USE "APPLICATION FOR PER	OF PLUG BACK TO A		
2 Name of Operator Hertragen—Petroleum—Corporation 3. Address of Operator P.O. Box 1737 - Roswell, NM 88202 Well Leater P.: 330 Feet From The South Lice and 990 Feet From The East Lice Section 26 Township 85 Range 28E NMFM Chaves County 10. Elevation (Show whether DF, RGE, RT, GR, etc.) 3936 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON XX TEMPORARILY ABANDON CHANGE PLANS CHANGE DELLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PULL OR ALTER CASING DITHER: 12. Describe Proposed or Completed Operations (Clearly state all perintent details, and give perintent date, including entinated date of starting any proposed world) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 100' cement plug from 1965' to surface (surface casing shoe @ 114'). **Validate V/main of the information bove is true to prompiate to be date of by bowinder and band. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Walter of Windows** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing Procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing Procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. pri				Twin Lakes San Andres Unit	
### Address of Operator Address of Operator		WELL OTHER			
3. Addres of Operator P.O. Box 17: 7 - Roswell, NM 88202 4. Well Location Unit Letter P: 330 Feet From The South Line and 990 Feet From The East Line Section 26 Township 85 Ruspe 28E NMPM Chaves County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3936 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: FERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. The dyser feet State United Starting and Transfer to Starting and Transfer Incidence of Starting and Transfer Incidence o	•	roleum Corporation //		1	
Well Location Unit Letter P : 330 Feet From The South Line and 990 Feet From The East Line Section 26 Township 85 Range 28E NMPM Chaves County 3936 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X COMMENCE DRILLING OPNS. PLUG AND ABANDON NET TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. 12. Describe Proposed or Completed Operations (Clearly state all perminent details, and give perminent dates, including entimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mmd & set 100' cement plug from 1965' to 1865' (across Tesan Andres). 3) Fill hole w/mmd & set 100' cement plug from 1965' to 1865' (across Tesan Andres). 4) Set Dry Hole marker & clean up location Notify NNOCD in Artesia 24 hrs. prior to commencing procedure. Thereby certify that the information dows is true appropriate to the total of by knowledge and beind. Thereby certify that the information dows is true appropriate to the total of by knowledge and beind. Thereby certify that the information dows is true appropriate to the total of by knowledge and beind. Thereby certify that the information dows is true appropriate to the total of by knowledge and beind. The propose for State Uteo) The propose for State Uteo)	3. Address of Operator	//	<u> </u>	·	
Section 26 Townstip 8S Range 28E NMPM Chaves County 10. Elevation (Slow whither DF, RKB, RT, GR, etc.) 3936 GR		7 - Roswell, NM 88202		Twin Lakes San Andres (Assoc.)	
Section 26 Townstip 8S Range 28E NMPM Chaves County 10. Elevation (Slow whither DF, RKB, RT, GR, etc.) 3936 GR	Unit Letter P	: 330 Feet From The South	Line and990	Feet From The East Line	
10. Elevation (Show whicher DF, RKB, RT, GR, atc.) 3936 GR 11. 12. 12. 12. 13. 13. 14.	20	00	200		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 150' to surface (surface casing shoe @ 114'). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notifie w/hoco to to surface to the location must be be lated of my bowinding and belief. **SIONATURE** Michael G. Hanagan The President DATE 5/13/98 TREPIONE NO. 505/623- (This space for State Use)		10. Elevation (Show whether L		NMPM Chaves County	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OF TEST AND CEMENT JOB COMMENT JOB COMMENT JOB CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENT JOB CASING TEST AND CEMENT JOB CASI			····	<u> </u>	
PERFORM REMEDIAL WORK PLUG AND ABANDON X FEMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting arry proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location) Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notife NMOCD in Artesia 24 hrs. prior to commencing procedure. **The OR PRINT NAME** Michael G. Hanagan **The President DATE 5/13/98 **THE PRESIDENT NAME** **THE OR PRINT NAME** **MICHAEL SALING AND ABANDONNENT DEPRINT NAME** **THE OR PRINT NAME** **THE OR PRINT NAME** **THE OR PRINT NAME** **MICHAEL SALING AND ABANDONNENT DEPRINT NAME** **THE OR PRINT NAME** **THE OR PR	MOTICAL OF MARKET AND A CONTRACT OF THE CONTRA				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notific NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notific NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notific NMOCD in Artesia 24 hrs. prior to commencing procedure. **Thereby certify that the Information above is true and complete to the boat of my browledge and belief. **SIONATURE** **THE President** **DATE 5/13/98** **THEPHONE NO. 505/623- (This space for State Use)	NOTICE	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notifier NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notifier NMOCD in Artesia 24 hrs. prior to commencing procedure. **Thereby certify that the information above is true motionomplate to the test of my knowledge and belief. SIGNATURE	PERFORM REMEDIAL WOF	MEDIAL WORK PLUG AND ABANDON X FIEMEDIAL WORK ALTERING CASING			
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location) Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Increty certify that the information above is true suppompted to the took of my knowledge and besid. **SIGNATURE** TIME President DATE 5/13/98 TYPEOR PRINT NAME Michael G. Hanagan TELEPHONE NO. 505/623-	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. DPLUG AND ABANDONMENT		
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **TOPE OR PRINT NAME** Michael G. Hanagan **TOPE OR PRINT NAME** Michael G. Hanagan **TOPE OR PRINT NAME** **TOPE OR PRINT NAME** **TOPE OR PRINT NAME** Michael G. Hanagan **TOPE OR PRINT NAME** **TOPE OR PRINT NAME** **TOPE OR STATE Use State Use)	PULL OR ALTER CASING				
Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Thereby certify that the information shows is true and complete to the test of my knowledge and belief.** **SIGNATURE** **Inna** **Inna** **President** **DATE** **DATE** **5/13/98** **TOPE OR PRINT NAME** **Michael G. Hanagan** **TELEPHONE NO. 505/623-**	OTHER:	· □			
Propose to plug and abandon as follows: 1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location. Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **SIGNATURE** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my knowledge and besid.** **Thereby certify that the information shows is true and complete to the test of my kn	12. Describe Proposed or Com	pleted Operations (Clearly state all pertinent details, an	d sive pertinent dates, inclu	which estimated date of starting any proposed	
1) Set CIBP @ approx. 2560' (Top perf. @ 2571') & cap w/ 35' cement plug. 2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location. Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Interpretation bove is the and complete to the best of the bost of the provided best of the procedure. **The OR PRINT NAME** Michael G. Hanagan **TELEPHONE NO. 505/623- (This space for State Use)	work) SEE RULE 1103.		a group per tomora manas, mora	and a service and of saving any proposed	
2) Fill hole w/mud & set 100' cement plug from 1965' to 1865' (across T/San Andres). 3) Fill hole w/mud & set 150' cement plug from 150' to surface (surface casing shoe @ 114'). 4) Set Dry Hole marker & clean up location. Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Notify NMOCD in Artesia 24 hrs. prior to commencing procedure. **Intervolventily that the information above is true and complete to the best of my knowledge and bedief. **Sinnature** Michael G. Hanagan **Type or Print NAME** Michael G. Hanagan **Telephone no. 505/623-** (This space for State Use)	Propose to plu	g and abandon as follows:			
# Not the NMOCD to Utiniss Plussing Operations. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE TYPE OR PRINT NAME Michael G. Hanagan Telephone No. 505/623- (This space for State Use)	2) Fill hole 3) Fill hole @ 114').	w/mud & set 100' cement plug fr w/mud & set 150' cement plug fr \fatecate 4'/2" cri	rcm 1965' to 18 rcm 150' to sur	65' (across T/San Andres).	
# Not the NMOCD to Utiniss Plussing Operations. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE TYPE OR PRINT NAME Michael G. Hanagan Telephone No. 505/623- (This space for State Use)	Notify NMOCD i	n Artesia 24 hrs. prior to com	mencing procedu	re.	
TYPE OR PRINT NAME Michael G. Hanagan Telephone No. 505/623- (This space for State Use)	-		J [3 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -		
TYPE OR PRINT NAME Michael G. Hanagan Telephone No. 505/623- (This space for State Use)				A.	
TYPE OR PRINT NAME Michael G. Hanagan Telephone No. 505/623- (This space for State Use)			_		
TYPE OR PRINT NAME Michael G. Hanagan Telephone No. 505/623- (This space for State Use)	* Notifie NMC	CO to Witness Plugging Operation	205.	12 144 114 114 114 114 114 114 114 114 114	
TYPE OR PRINT NAME Michael G. Hanagan TELEPHONE NO. 505/623- (This space for State Use)	I hereby certify that the informati	on above is true and complete to the best of my knowledge and	belief.	Profession and the second	
(This space for State Use)	SIONATURE	TO ISO THE TIME TO THE TANK TH	Presiden	t	
	TYPE OR PRINT NAME	Michael G. Hanagan		TELEPHONE NO. 505/623-50	
	(This space for State Use)				
3 3 4 D 3 1 F T 1 1 D 3 1 T 1 T 1 D 3 1 T 1 T 1 D 3 1 T 1 T 1 D 3 1 T 1 T 1 D 3 1 T 1 D 3 1 T 1 D 3 1	•	0000 200	Eal Page T	t Mau 21. Gú	