OF COPIES RECEIVED 2			Form C-103 Supersedes Old
DISTRIBUTION			C-102 and C-103
SA AFE	NEW MEXICO OIL CONS	ERVATION	Effective 1-1-61
FILE			5a. Indicate Type of Lease
LAND OFFICE		DEC -1 1980	State X Fee
OPERATOR			5. State Oli & Gas Lease No.
		0. C. D.	LG-3160
SUNDRY NOTICES AND REPORTS ON WELLS OFFICE			
USE "APPLICATI	ON FOR PERMIT _** (FORM C-1011 FOR SUL	H PROPOSALS.	7. Unit Agreement Name
OIL GAS WELL X	0THER-		8. Form or Lease Name
2. Name of Operator General American Oil Company of Texas			G.A.O. State
P. O. Box 128 Loco Hills, New Mexico 88255			9, Well No. #1
4. Location of Well			10. Field and Pool, or Wildcat Undesignated
THE North LINE, SECTION 36 TOWNSHIP 7-South RANGE 28-East HMPM.			
	15. Elevation (Show whether 4050.7 G.L		12, County Chaves
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER	[]		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
October 9, 1980 Ran Dresser Atlas Gamma Ray Tie-In-Log. Perforated Fusselman as follows: 6952'-6958' 2 shots per foot 6989'-6996' 2 shots per foot Set Packer @ 6658'. Swab Tested. No Show. Set 5-1/2" "Charger" cast iron bridge plug			
at 6940' K.B. Dumped 30' of cement on bridge plug with dump bailer. P.B.I.D. now 6910 .			
October 15, 1980 Rigged up Dresser Atlas and perforated Fusselman as follows: 6866'-6879' 2 shots per foot.			
Set Packer @ 6658' — Swab tested — No shows.			
October 21, 1980 Rigged up Dresser Atlas and perforated Fusselman as follows: 6782'-6800' 2 shots per foot 6812'-6820' 2 shots per foot			
Swab Tested — No shows.			
October 23, 1980 Unseated packer. Spotted 3 barrels 15% M.C.A. acid across perforations. Set packer. Pressure annulus to 500 PSI. Formation started feeding at 1500 PSI. Put acid away and shut down. ISIP: 1200 PSI. Bled casing down and started to swab well. Swab well down. Treated with additional 750 gallons of 15% M.C.A. Acid. Flushed with 2% KCL water. ISIP: 1600 PSI. Left well closed in for 30 minutes prior to swabbing. Swabbed nine runs and well was swabbed down to seating nipple. (Over)			
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
APPROVED AV MALE Million TITLE Field Superintendent DATE November 24, 1980			
APPROVED BY THE	Man TITLE_	OIL AND GAS INSPECTOR	DED1_0_1200

CONDITIONS OF APPROVAL, IF ANY:

ctober 23, 1980 (Continued) Continued to swab well. No shows of oil or gas.

- ctober 27, 1980 Unseated packer and pulled from hole. Set Dresser Atlas "Charger" cast iron bridge plug at 6770' and dumped 30' of cement on top of bridge plug. P.B.T.D. now 6740' K.B.
- Control States State
- October 29, 1980 Tubing pressure was 1850 PSI. Flowed well for 5-1/2 hours estimated rate is 410 MCF per day. Well is presently shut-in awaiting on pipeline connection.