

U.S.C.D. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or to change a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 14294	
2. NAME OF OPERATOR McClellan Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Post Office Drawer 730, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 660' FWL		8. FARM OR LEASE NAME "MP" Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, HT, GR, etc.) 3744.6 G.L.		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5-T9S-R26E	
		12. COUNTY OR PARISH Chaves	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well in following manner:

1/26/81: Cut tubing (2-7/8") off at 4400' with wireline chemical cutter.
Left Baker Model R in hole set at 4405'.
Shot off 4 1/2" casing at 3800' and pulled all casing from 0-3800'.

1/27/81: Spotted 20 sack Class C plug from 4400' to 4250'.
Spotted 35 sack plug from 3750' to 3850'.
Spotted 35 sack plug from 1950' to 2050'.
Spotted 45 sack plug from 850' to 950'. Waited 4 hours and tagged plug at 837'.
Spotted 10 sack plug at surface and installed dry hole marker.

Pits and location will be leveled after sufficient time to allow pits to dry.

18. I hereby certify that the foregoing is true and correct

SIGNED Paul Raydale TITLE Engineer

DATE 2/05/81

(This space for Federal or State office use)

APPROVED BY PETER W. CHESTER

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

FOR

JAMES A. GILLHAM*
DISTRICT SUPERVISOR

See Instructions on Reverse Side