ש בשמשניו עו בריב וטח.	CFAF	1 I IVIE
	-	
DITRIBUTION		
SANTA FE	Tī	Ī
FILE		1/
U.S.G.S.		
LAND OFFICE		
OPPRATOR		1

L CONSERVATION DIVISION

Form C-103

C/ 1 10

DEFRIBUTION		Ρ. C). BOX 208	8 8			Revised 1	10 1 74
SANTA FE		SANTA FE,	NEW ME	XICO 8750	1		MEAL2EG A	19-1-70
FILE	1. 2.				1389	Sa. Indicate Ty	oe of Leuse	
U.S.G.S.				٠.	. 000	State		• [X]
LAND OFFICE						5. State Oil & C		
OPERATOR	لسلسل				n en		740 21 401 7107	
				<u></u>	20 88A, GATON	mm	mmm	rrr
(DO BCT USE THIS FOR	SUNDRY NOTICES	AND REPORT	S ON WEL	LS	ESERVOIR,			
1. OIL X GAS WELL X WELL	OTHER-					7. Unit Agreeme	ent Name	
2. Name of Corator						8. Form or Leas	se Name	
RALPH NIX	\checkmark					AL		
3. Address of Operator						9. Well No.		
D O Boy A	517, Artesia,	New Mexic	co 882	10		1 1		
4. Location of well	or a reside	New Mexic	002	10	····	10. Field and F	ool, or Wildcat	
	990	F:	ac+	9.0	n	Wild	lcat SA	
UNIT LETTERP	990	T FROM THE	15 C	E AND	FEET FROM	Tititi		<i>UZZ</i> .
Court la	2.4		7c		28_5			1111.
THE SOUTH	INE, SECTION24	TOWNSHIP	7-5	RANGE	NMPM.			1111.
mmmm	THE THE PARTY OF T	Elevation (Show u	Lasker DE R	T CP atc.		12. County	774444	444
	//////////////////////////////////////		mether Dr. K	1, ON, ELC.)		1		
<u> </u>	711111111	4011' GR				Chaves	_777777	7777.
16.	Check Appropriate	Box To Indic	ate Nature	e of Notice,	Report or Oth	er Data		
NOTIC	E OF INTENTION	TO:	1		SUBSEQUENT	REPORT OF	·:	
PERFORM REMEDIAL WORK		PLUG AND ABANDO	N . REMI	EDIAL WORK		ALTE	RING CASING	
TEMPORARILY ABANDON]		сом	MENCE DRILLING	OPNS.	PLUG	AND ABANDONME	HT []
PULL OR ALTER CASING		CHANGE PLANS	CA51	NG TEST AND CE	MENT JOB			
	,		_ 。	THER	erf & aci	d		_[]
OTHER			_ [] [_				
								
17. Describe Proposed or Cor work) SEE RULE 1103.	npleted Operations (Clea	irly state all pertino	ent details, a	nd give pertiner	nt dates, including	estimated date of	f starting any pr	oposed
10/20/80	Perforated a	+ 2672 7	3 74	75 with	4 shots			
10/20/80	Acidize with				. Diloco.			
	Swabbed back	-		o dela.				
10/22/80	Acidize with			FFF acid	7			
10/22/80	Swabbed back							
10/22/90	Perforated a					+ c		
10/23/80	Set bridge p			05, 00 V	vicii 5 5110	CD .		
		1500 ~	JO. Sign Ne	ነውው ጋብያ :	acid 420 ga	al. water		
	Acidize with							
	Swabbing bac	ok actu wa	ter and	n Small (JUL OI OII	•		

18. I hereby cer	rify that the information above is true and	complete to the bes	t of my knowledge and belief.		
BIGHED	Soul fles p	TITLE	Operations Manager	DATE_	10/28/80
APPROVED BY	Wa Gressia	7171.6	COOM WASON, WALL MANNE LA	DATE_	NO/ 0 5 1252