

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 1 1982

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
Fee Lease

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator McClellan Oil Corporation
3. Address of Operator P.O. Box 730, Roswell, NM 88201
4. Location of Well UNIT LETTER <u>M</u> <u>860</u> FEET FROM THE <u>South</u> LINE AND <u>560</u> FEET FROM THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>6-S</u> RANGE <u>27-E</u> NMPM.

7. Unit Agreement Name
8. Farm or Lease Name Jack L
9. Well No. 2
10. Field and Pool, or Wildcat Wildcat <u>obo.</u>

15. Elevation (Show whether DF, RT, GR, etc.) 4106' G.L.	12. County Chaves
---	----------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned as follows:

6-21-82: Set 40 sack Class "C" plug at 5000'. Tagged at 4850'.  
Set 30 sack Class "C" plug at 4450'.  
Ran free point on 7" casing and shot off at 2900'. Pulled 2900' of 7" casing.  
Set 40 sack Class "C" plug at 2945'. Tagged at 2795'.  
Set 40 sack Class "C" plug at 2660'.  
Set 50 sack Class "C" plug at 1504' inside & out of 9-5/8" casing.  
Tagged at 1364'.  
Spotted 10 sack plug at surface and installed dry hole marker.  
Salt mud was used between all plugs.  
Location to be cleaned and ripped after pits dry.

*Partial P+H  
FD-2  
7-9-82*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Ruel Ragsdale</u>	TITLE <u>Operations Manager</u>	DATE <u>6-29-82</u>
APPROVED BY <u>Darryl Bruce</u>	TITLE <u>Geologist</u>	DATE <u>10/6/83</u>
CONDITIONS OF APPROVAL, IF ANY:		