

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NOV 02 '87

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

O. C. D.

ARTESIA, OFFICE

3a. Indicate Type of Lease State ☐ Fee ☒
3. State Oil & Gas Lease No. N/A
7. Unit Agreement Name N/A
8. Farm or Lease Name O'Brien "F"
9. Well No. 8
10. Field and Pool, or Whichever Twin Lakes-San Andres Assoc
12. County Chaves

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Pelto Oil Company

3. Address of Operator
500 Dallas Street, Suite 1800, Houston, TX 77002

4. Location of Well
UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 25 TOWNSHIP 8S RANGE 28E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3954 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Propose to Plug and Abandon well as follows:

1. Notify NMOCD of time P&A operation will begin.
2. Spot 40 sx Class "C" Cement from PBTD 2680'± to 2548'±.
3. Load 8-5/8" 20# casing w/10#/G salt gel mud.
4. Tag top of plug @ 2548'±.
5. Spot 30 sx Class "C" cement plug 1600'-1500'.
6. Spot 30 sx Class "C" cement plug 850'-750'.
7. Spot 30 sx Class "C" cement plug 350'-450'.
8. Spot 10 sx Class "C" cement plug from 36' to surface.
9. Cut off 8-5/8" casing below ground level and install dry hole marker as per NMOCD rule 202A. Clean location and cover work pit. Cut off deadmen anchors.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert L. Spotswood TITLE ENGINEERING MANAGER DATE 9/21
Original Signed By Mike Williams
Oil & Gas Inspector Notify N.M.O.C.C. in sufficient time to witness DATE NOV 1

