	CIST
Submit 3 Copies To Appropriate District State of New Mex	ico Form C-103
Office Energy, Minerals and Natura	al Resources Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II OIL CONSERVATION I	30005-60807
811 South First, Artesia, NM 88210OIL CONSERVATION IDistrict III2040 South Pache	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 875	$ $ STATE \Box FEE \Box
2040 South Pacheco, Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-104) FOR PROPOSALS.)	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-100 FOR PROPOSALS.)	R SUCH Twin Lakes San Andres Unit
1. Type of Well:	
Oil Well Gas Well Other Injection 2. Name of Operator N	RECEIVED 7 Well No.
Concho Oil & Gas Corp. 00	CD - ARTESIA 59
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701	*8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)
4. Well Location	2229252 11 1 1 1 1 1 1 1 1 2 2 9 5 2 5 5 2 5 5 2 5 5 5 5 5 5 5 5 5
Unit Letter_ C :330_Feet from theNorth line	and 1750 feet from the <u>West</u> line
Section 6 Township 9S Ra 10. Elevation (Show whether DR,	ange 29E NMPM Chaves County RKB_RT_(CR_etc.) Image: County Image: County Image: County
4001.7 GR	建成重要的基本。在中国的基本中,
11. Check Appropriate Box to Indicate Nat	ture of Notice, Report or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK D PLUG AND ABANDON	SUBSEQUENT REPORT OF: REMEDIAL WORK
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. C PLUG AND ABANDONMENT
PULL OR ALTER CASING DULTIPLE COMPLETION	CASING TEST AND CEMENT JOB
_	\mathbf{H}
OTHER:	OTHER: Perform MIT/Acidize/Return to Inj
12 Describe proposed or completed operations. (Clearly state all pert	inent details, and give pertinent dates, including estimated date
12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple C	inent details, and give pertinent dates, including estimated date
12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Co or recompilation.	inent details, and give pertinent dates, including estimated date
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU Release pkr & tag bottom @ 2702' (PBTD @ 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg.
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2860'). POH w/ tbg. & could not make any hole. POH w/ bailer. TIH w/ 3-7/8"
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'.
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2860'). POH w/ tbg. & could not make any hole. POH w/ bailer. TIH w/ 3-7/8"
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested the tag of the tag. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% H 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'.
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% F back all/oad wtr. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 1 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr.
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested the tag of the tag. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% H 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 1 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr.
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% F back all/oad wtr. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 1 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr.
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% H back all/load wtr. 06-07-01 Return well to injection @ 71 BPD @ 920 psi. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 1 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. Pentol 300 and flush to top perf w/ prod wtr. Flow & swab
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% F back all/oad wtr. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 1 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. Pentol 300 and flush to top perf w/ prod wtr. Flow & swab
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2" R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% H back all/load wtr. 06-07-01 Return well to injection @ 71 BPD @ 920 psi. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 1 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. Pentol 300 and flush to top perf w/ prod wtr. Flow & swab
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2'' R4 pkr & tested th 05-30-01 Tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% H back all load wtr. 06-07-01 Return well to injection @ 71 BPD @ 920 psi. 	inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2 2860'). POH w/ tbg. 2 & could not make any hole. POH w/ bailer. TIH w/ 3-7/8" bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. Pentol 300 and flush to top perf w/ prod wtr. Flow & swab
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2'' R4 pkr & tested the tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% Heack all/load wtr. 06-07-01 Return well to injection @ 71 BPD @ 920 psi. 	 inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2860'). POH w/ tbg. bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. Pentol 300 and flush to top perf w/ prod wtr. Flow & swab Dest of my knowledge and belief. <u>Production Analyst</u> DATE 6-11-01
 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple Coor recompilation. 05-21-01 Tested annulus to 300#. Ok. 05-24-01 MIRU. Release pkr & tag bottom @ 2702' (PBTD @ 05-25-01 TIH w/ bailer. Tagged @ 2702'. CO to 3' of soft fill bit. RU rev unit & CO to 2860'. 05-29-01 FTOH w/ bit & collars. RU 4-1/2'' R4 pkr & tested the tested annulus to 360#. (Chart attached) RD. 06-04-01 Pump 500 gals Xylene, 11.1 bbls prod water w/ 5 gal SI. 06-06-01 Swab & flow back load. Acidize w/ 2000 gals 15% Hested attached wtr. 06-07-01 Return well to injection @ 71 BPD @ 920 psi. 	 inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion 2860'). POH w/ tbg. bg in hole. Set pkr @ 2649'. s TC 420 and 2 drums TC 405. Flush to top perf w/ prod wtr. Pentol 300 and flush to top perf w/ prod wtr. Flow & swab Dest of my knowledge and belief. <u>Production Analyst</u> DATE 6-11-01

(This space for State use	À		
APPPROVED BY	Keind	only	
Conditions of approval,	if any:		ĺ