

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

APR 22 1981

O. C. D.

ARTESIA, OFFICE

3a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-5252

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amax Petroleum Corporation	8. Farm or Lease Name Amoco State
3. Address of Operator P. O. Box 42806, Houston, Texas 77042	9. Well No. 1
4. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM West 1 LINE, SECTION 1 TOWNSHIP 8-S RANGE 27-E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3949' GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-30-81 TD 7033', PBTD 2,650'. MI completion unit, ran CBL/CCL log.
4-01-81 & Perforated San Andres from 2,538'-48' & 2,551' - 54', acidized w/500
4-02-81 gals. 15% MCA - Swb dry.
4-03-81 Set bridge plug @ 2,500' dumped 5 SX. cement plug on top. Perforated
thru San Andres from 2,160-68' & 2,172'-78'. Acidized w/500 gals. 15%
4-04-81 MCA. Acidized w/5,000 gals. 28% NE FE acid. Swb. 43 bbls load water
w/trc. oil.
4-08-81 Swabbed dry. Set 35 sx cement plug from 400'-300' and 15 sx plug
in top. Cut off casing welded on cap and installed marker pipe.
Released completion rig. Well P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alfred E. B. L. TITLE Vice President DATE 4-13-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: