

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Fred Pool Drlg. Inc. ✓		5. State Oil & Gas Lease No.
3. Address of Operator 1300 Clovis Star Rt. Roswell, N.M. 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>W</u> LINE AND <u>1980</u> FEET FROM THE <u>N</u> LINE, SECTION <u>4</u> TOWNSHIP <u>11S</u> RANGE <u>25E</u> N.M.P.M.		8. Farm or Lease Name Hondo River Farm Com
		9. Well No. 1
		10. Field and Pool or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3464.4 Gr		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>Plug back to bottom of 8 5/8</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Jan. 16, 1981

TD 5/8"

Plug back to bottom of 8 5/8: Set plugs at 5050 ft. to 4950, used 35 sacks cement.
4375 to 4225 " " "
3700 to 3600 " " "
2950 to 2850 " " "
1500 to 1400 " " "
1325 to 1170 used 50 sacks cement.

Pulled pipe up to 1000 ft., went back to plug, tagged top of plug at 1159 ft.
Plugs down at 8 p.m.

Intend to perforate and acidize the San Andres formation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Santa Fe Pool

TITLE Secretary

DATE 1-24-81

APPROVED BY Mrs. Williams

TITLE OIL AND GAS INSPECTOR

DATE

JAN 30 1981