TD STATES DEPARTM. OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. FORM APPROVED

6. If Indian, Allottee or Tribe Name

N/A

OMB No. 1004-0135	01.	•
Expires November 30, 2000		
5. Lease Serial No.		_
NM33943		

				7. If Unit or CA/Agreement, Name and/or No.			
	UBMIT IN TRIPLICATE -	Other Instructions on re	everse side	IN/A			
1. Type of Well Oil Well	Gas Well	Other	1234567	8. Weil Name and No.			
2. Name of Operator	<u> </u>			20 \			
Yates Petroleum Co	orporation /			9. API Well No. 30-005-60865			
3a Address		3b. Phone No. (include	de area code)	ರು 10. Field and Pool, or Exploratory Area			
105 S. 4th Street - A		505-748-1471	RECEIVED OCD ARTESIA	4			
Location of Well (Footage, Se	c., T.,R., M., or Survey Desci	nption)	UCD - ARTESIA	PECOS SLOPE ABO 11. County or Parish, State			
660' FNL & 1980' FWL Section 15-T9S-R24E UNIT C							
CHAVES COUNTY, NM							
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA YPE OF SUBMISSION TYPE OF ACTION							
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	V/ater Shut-Off			
Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Cther			
	Change Plans	Plug and Abandon	X Temporarily Abandon				
	Convert to Injection	Flug Back	Water Disposal				
		_	•	roximate duration thereof lif the proposal is to deepen			
YATES PETROLEUM CORPORATION RESPECTFULLY REQUESTS PERMISSION TO TEMPORA RILY ABANDON AS FOLLOWS: 1. MIRU WSU & safety equipment. Bleed pressure off tubing & load tubing & casing w/ 30+/- bbls of 2% KCL water; ND wellhead & NU BOP. POH w/ tubing & seat nipple; pump 2% KCL water only as needed to keep well dead. 2. RU wireline & RIH w/ 4-1/2" guage ring to 3350' to make sure casing is clear, then run 4-1/2" CIBP & set plug @ 3350' - cap plug w/ 35' of cement. RD wireline. 3. RIH w/ tubing to 3315' & circ hole w/ 10.0 ppg brine plugging mud w/ 25# of gel/ bbl mud then close BOP & test casing to 500 psig for 30 minutes and record a chart for NMOCD. POH laying down tubing; cap wellhead & temporarily abandon the well.							
hereby certify that the foregoing is	true and correct						
Name (Printed/Typed)			Title				
Donna Clack	$ \lambda$	· · · · · · · · · · · · · · · · · · ·	Operations Technicia	n			
Signature	Clark		Date 5-14-02				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by		MMOCO	Title	Date			
Conditions of approval, if any, are all the applicant holds, egal or equitable applicant to conduct operations their	ttached. Approval of this notice of e title to those rights in the object lean	pes not warrant or certify that t lease which would entitle the	Office				
Title 18 U.S.C. Section 1001 and Ti	tle 43 U.S.C. Schon 1212, make	it a crime for any person knowin	gly and willfully to make to any departmen	t or agency of the United States any faise, fictitious			