Subm.t 3 Copies To Appropriate District State of New Mexico		C/2,01	Form C-103
Subm.t 3 Copies To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Resources		WELLADING	Revised March 25, 1999
District II		WELL API NO. 30005-60886	
District III 811 South First, Artesia, NM 88210 District III  RECFIVED 2040 South Pacheco		5. Indicate Type of	of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 OCD - ADJECT Santa Fe NIM 87505		STATE FEE 6. State Oil & Gas Lease No.	
District IV 2040 South Pacheco, Santa Fe, NM 87505		6. State Oil & G	as Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Twin Lakes San Andres Unit	
1. Type of Well: / Oil Well Gas Well Other Injection			
2. Name of Operator Concho Oil & Gas Corp.		7. Well No. 72	
3. Address of Operator		8. Pool name or Wildcat	
110 'W. Louisiana Ste 410; Midland, Tx 79701  4. Well Location		Twin Lakes; San Andres (Assoc)	
Unit Letter H: 1650 Feet from the NORTH line and 990 feet from the EAST line			
Section 6 Township 9S Range 29E NMPM Chaves County			
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3963.3'GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. DPLUG AND ABANDONMENT		
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB	D 🗆	/
OTHER:	OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation. 12-04-01 Notified OCD, Mike Stubblefield. MIRU Triple N, rig #25. ND WH & POH w/ 10 jts. RIH w/ gauge ring on WL &			
stacked out @ 570'. POH w/ gauge ring. RIH w/ mule-shoed sub & 36 jts. Hit csg collapse / part @ 949'. Worked tbg to 1122'. Unable to get deeper. POH w/ tbg. RIH w/ mule-shoed & bent sub to collapse / part @ 949'. Unable to			
get past 1122'. POH & SDON. 12-05-01 ND 8-5/8" WH & PU on 4-1/2" csg, parted @ + / - 1122' per weight indicator. NU WH & RIH w/ bent mule-shoed sub,			
tagged PBTD @ 2720'. RU cementer & loaded hole w/ mud. Pumped 25 sx C cmt 2720' – 2357'. PUH w/ 17 stds & WOC 3-1/2 hrs. RIH w/ 12 stds & tagged cmt @ 2365'. POH w/ tbg to 1929'. RIH w/ WL & perf csg @ 2180'. POH			
w/ WL. RIH w/ tbg to 2180' & pumped 40 sx C cmt 2			
up on csg. SDON. 12-06-01 RU csg tools & LD 14 jts 4-1/2" 9.5# csg. RD csg tool	ls. RIH w/ mule-shoe	ed bent sub. Unable	e to get in csg stub @
575'. POH w/ tbg. RIH w/ mule-shoed straight sub &	worked into csg. C	ont in hole to 1043	'. Loaded hole &
pumped 60 sx C cmt 1043' – 464'. POH w/ tbg, hangi 537'. Pumped 50 sx C cmt 537' – 342'. POH w/ tbg 8		3-1/2 nrs & RIH W/	tog. I agged plug @
12-07-01 RIH w/ tbg & tagged cmt @ 411'. POH w/ tbg to 189' & circ 95 sx 189' to surface. P & A FINAL REPORT			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE TITLE	Production Analy		12-11-01
Type or print name Terri Stathers Telephone No. 915/663-7443  (This space for State use) FEB 6 2002			
APPPROVED BY TITLE	Sulo &	W &	_DATE
Conditions of approval, if any:		I	

Post Pr A