


4/5

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. CIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-36652	
2. NAME OF OPERATOR Mesa Petroleum Co. ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 2009, Amarillo, Texas 79189		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 660' FEL		8. FARM OR LEASE NAME Barn Federal	
		9. WELL NO. 3	
		10. FIELD AND POOL, OR WILDCAT West Pecos Slope Abo	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13, T8S, R22E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4110' GR	12. COUNTY OR PARISH Chaves	13. STATE NM



16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to P&A well as follows:

Set CIBP @ 2810' (Abo perms 2854'-2940') plus 35' cement
Set 100' plug (8 5/8" csg set @ 1198') from 1248'-1148'
Set 50' plug to surface
Install dry hole marker

XC: BLM-R (0+2), NMOC-D-A, WF, CR, Reg., Acctg, Expl, Land, Partners

18. I hereby certify that the foregoing is true and correct

SIGNED

R.E. Mack

TITLE

Regulatory Agent

DATE

12-3-85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

DEC 12 1985

*See Instructions on Reverse Side