NU. OF COPIC	5 PFCLIVED			-	-	Form C-103 Supersedes Old	
SANTA FE	DISTRIBUTION NEW MEXICO			O OIL CONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65	
F1LE U.S.G.S.	· · · · · · · · · · · · · · · · · · ·		30-005-60925		Sa. Indicate Type of Leana State X Fee		
LAND OFFIC	)					State [A] Fee [_] S. State Off & Gas Leave No.	
						L-5347	
SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED.							
L. OIL GAS WILL OTHER-				FEB 2 3 19	7. Unit Agreement Name Campbell Station Unit 6. Form of Lease Name		
Carl A. Schellinger				O. C. D.		Campbell Station Unit	
2. Address of Operator P.O. Box 447, Roswell, New Mexico 88201						1	
4. Lecation of V	Nell M	660 FERT FROM THE	South	LINE AND 660	FEET FROM	10. Field and Fool, or Wildean Wildcat	
тне Ше	est Line, sec	110N 34 TOWNS	8-S	BANGE 27-E			
IIIIII				DF, RT, GR, etc.) VB		12. County Chaves	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other						the support of the second s	
		INTENTION TO:	1	•		REPORT OF:	
PERFORM REMED	DIAL WORK	PLUG AKO	ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY A	F	CHANGE PI		COMMENCE DRILLING OPNS.	ав — ] ав	PLUG AND ABANDONMENT	
				OTHER Rig Up Dua	al Compl	etion Equipment [X]	
0THER			L.J				
work) SEE	RULE 1103.					estimated date of starting any proposed	
1/26/82 Move in and rig up Superior Well Service completion unit and Star Tool Co., reverse p Shut in tubing pressure 1100 PSI							
	Blow well dow	wn, pump 2% KCL wa	ter down a	annulus to displac	ce gas a ft rovo	nd kill well. Pick up	
	more tubing and run on in hole, tag sand at approx 5500 ft, reverse sand off of RBP, approx 65 ft of sand, circ. hole clean.						
	Release RBP and pull to approx 5100 ft, above Abo perfs. and secure well for the day at 3:00 P.M. Baker tool man did not have all his equipment.						
1/27/82	No pressure	ressure on wellhead, load and circ. hole w/2% KCL water and wait on Baker Packers.					
	Baker Packer	Baker Packer's man and blast joints show up at 11:00 A.M. Trip out of hole with RBP. Rig up and run in hole with Baker, Lok - Set Packer, on and off tool, Baker Sliding					
	sleeve (1.87	I.D.) 70 ft. of B	aker blast	t joints and flang	ge up we	11head, w/10,000# of	
	tension pulled on tubing, as per diagram and talley.						
1/28/82	Swab load water off of Abo perfs through sliding sleeve and up tubing as hard as possible for 10 hours, nothing but water, very little gas.						
1/29/82	1/29/82 Shut in tubing pressure 150 PSI; backside - 200 PSI Swab load water but trying to gas a little. After approx. 6 hours of swabing, well kicks off and starts to flow water on it						
1/30/82	own with gas increasing. Flow well on 3/4" choke until sundown to clean up. Shut in tubing pressure 400 PSI and 700 PSI on annulus. Open well to pit and flare to						
_, _ ,	clean up Abo	through tubing, g	as wet bu	t burning. Flow	tries to	die, run swab.	
18.1 hereby cers	ity that the information	tached Exhibit	e to the best of	my knowledge and belief.			
$\langle \cdot \rangle$	anlhou	$\sim$	, Ope	rator		2/10/32	
ZIGNED		<b>A</b>					
APPROVED BY	Wat	resset	SUP	BRVISOR, DISTRICE 3	<del>ور</del> الم	DATE FEB 2 0 1304	
-							

CONDITIONS OF APPROVAL, IF ANYI

Exhibit attached hereto and made a part of New Mexico Oil Conservation Commission Form C-103

1/30/82 After approx. 7 hours of flowing through tubing on full open choke, 3/4", well flowing w/5-10 PSI or tubing trying to dry up. Turn annulus to pit on 1/4 (16/64) choke for 1 hour, gas dry holding on 190 to 200 PSI - (est. 300 MCFD) Able to get 1 joint of 1 in. pipe down backside between 8 5/8 and 13 3/8. Mix 100 sks to fill hole and back in cellar. Secure well and shut down for day at 3:00 P.M. Shut in tubing pressure 700 PSI, annulus pressure 200 PSI. 2/1/82 Rig up and go in hole w/Jarrel Services, Inc. to close Baker sleeve, turn Abo up annulus. Sleeve at 5243 ft. ground level, 5253 K.B. Go in hole, pull Eq. pin in blanking plug. Go in hole, pull blanking plug in Lok-Set profile. Flow Penn to Pit to clean up Release all equipment. Well ready for production status.

Diagram of Dual Completion Set-up is attached Penn perfs will be produced through tubing and Abo perfs through the annulus, pursuant to OCD hearing. NOTE: C-102 is also attached to designate  $SW_{\frac{1}{4}}$  to Abo and  $S_{\frac{1}{2}}$  to Penn.

UPPEN LU STATS COMPAN CA LINEA TUBING TUBING WELL NAME SIZE & NUMBER X WEIGHT FIELD C COUNTY GRADE 05 - 16 E of STATE THREAD 1 IC U 15 X NEW 75-TH640C DATE 14 6303 **w.o**. 13 ITEM DESCRIPTION ESTIMATE 12 Pacher Ы Ike S 08 ennecto 81 Profile X 040.40 Tubing 55 -11 h s <u>n 1</u> 99 8 20 め 5177 98 20 9 Abd Perf Ю 10.05 06 10 D bmg 6 5229 5 big STHERE 4 4 3 31 15 6 7 e P 16 1a 2 6303 Ension pulled n ubm P 05.0 Penn Perfs 637 PREPARED FOR ser 4 PHONE 748-263 PREPARED BY OFFICE 6388 6023 NAVIGATION BOULEVARD P.O. BOX 3048 • HOUSTON, TEXAS 77001 TELEPHONE (713) 923-9351 • TELEX 76-2833 DIVISION OF BAKER OIL TOOLS GROUP, BAKER INTERNATIONAL CORPORATION