

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr., Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-005-60950

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
LG-9571

7. Lease Name or Unit Agreement Name:  
Boswell State

8. Well No.  
1

9. Pool name or Wildcat  
Pecos Slope Abo, West

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other Plug & Abandon ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter J : 1650 feet from the South line and 1650 feet from the East line

Section 30 Township 5S Range 21E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4258.3' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5-14-2002 - Moved in and rigged up pulling unit and plugging equipment. Bled well down to pit. Nippled down wellhead and nipped up BOP. Rigged up floor and 2-3/8" tubing equipment. Released packer. Shut well in for night.

5-15-2002 - POOH with 2-3/8" tubing and packer. Rigged up wireline. RIH with gauge ring to 2450'. POOH with wireline. TIH with CIBP and set CIBP at 2450'. POOH with wireline. Capped CIBP with 35' of cement. Rigged down wireline. RIH with tubing and tagged up at 2400'. Circulated hole with plugging mud. Spotted a 25 sack Class C Neat cement plug from 2400-2038'. POOH to 1500'. Shut well in for night.

5-16-2002 - POOH to 1050'. Spotted a 25 sack Class C Neat cement plug. POOH with tubing. WOC 4 hours. RIH with tubing and tagged plug at 702'. POOH with tubing. Rigged down tubing equipment and floor. Shut well in for night.

5-17-2002 - Nippled down BOP. Rigged up floor and 2-3/8" tubing equipment. RIH with tubing to 410'. Circulated 30 sacks Class C Neat cement from 410' to surface. POOH with tubing. WOC 2 hours. Cement stayed at surface. Rigged down plugging equipment and pulling unit. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

REPORT. Plugging completed 5-16-2002.

SIGNATURE Rusty Klein TITLE Agent for BCM & Associates DATE May 22, 2002

Type or print name Rusty Klein

Telephone No. 746-6565

(This space for State use)

APPROVED BY [Signature]

TITLE Field Rep ID

AUG 8 2002  
DATE

Conditions of approval, if any:

