		子 入 し し 丁 丁	H C C R S	C U A R T E R		ke Stubblefield parture 8:00 a.m.	•			
	10 × 0 × 0 × 0	Y		H O U R S	In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken. Signature					
	Ŋ	D	2	-	1 Well	I, 18-6-24, Mesa Petr. Corp. Lake Tank #1 P&A well OK to release.				
C.)	0	D	ן	2	1 Well	P, 35-4-24, Yates Petr. Corp. Redman "OY" St. #1 P&A well OK to release.				
н	0	D	1	-	l Well	11-5-24, Mesa Petr. Corp. Doris #2 Checked general operation of Dual Drlg. Rig #1.				
Н	0	D	-	2	l Well	17-5-25, Mesa Petr. Corp. Comer #2 Checked general operation of Desert Drlg. Co. Rig #1.				
Η	0	D	ו	-	1 Well	O, 1-6-24, Mesa Petr. Corp. Jess Fed. #3 Checked general operations of Tom Brown Drlg. Co. Rig #30.				
C	0	DDD-Well A, 17-10-25, Umex Inc. Cannon Fee #2 Cabletool is @ 450' fishing for tools lost in ho Will witness casing set @ 700'.						e.		
					<u>Mil</u> UIC RF7 .CtF	216	Per Diem UIC RFA Other 9.00	Hours UIC RFA Other	7	
TERECHED						INSPECTION CLASSIFICATION			OF SPECIFIC WELL 11.1TY_INSPECTED	
) (а - н - н - р - р - н - н - н - н - н - н - н - н - н - н	ouses Luggi Luggi ell T epair aterf Lisbap	eepla ng C. cst /Werl low or :	leanu p kov er	R = In $R = In$	derground Injection Con- lated to injection proje- sulting from injection : jection and production i sts, surface injection (spections relating to Re her - Inspections not re clamation Fund dicates some form of end eld (show inmediately be	Act, facility, or well of into any well. (SHD, 2) wells, water flows or pr equipment, plugging, etc aclamation Fund Activity elated to injection or 5 forcement action taken 5	$\begin{array}{cccc} p & - & P - & Pro\\ ndry & I & - & Inj\\ (c.s.ure) & C & - & Con\\ (c.s.ure) & S & - & Op\\ S & - & SWD\\ & & U & - & Und\\ The & G & - & Gen\\ The & G & - & Gen\\ F & - & Fac\\ In & One & O & Oth\\ \end{array}$	duction ection bined prod. inj. erations erground Storage eral Operation filty or location eting	