

Submit 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W Grand Ave, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

C15  
 Form C-103  
 Revised March 25, 1999

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-005-61132

5. Indicate Type of Lease  
 STATE  FEE

6. State Oil & Gas Lease No.  
 LG-5573

7. Lease Name or Unit Agreement Name:  
 Macho State

8. Well No.  
 2

9. Pool name or Wildcat  
 Pecos Slope Abo (West)

SUNDRY NOTICES AND REPORTS ON WELLS  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 Oil Well  Gas Well  Other

2. Name of Operator  
 McKay Oil Corporation

3. Address of Operator  
 PO Box 2014, Roswell NM 88202-2014

4. Well Location  
 Unit Letter F : 1980 feet from the North line and 1980 feet from the West line  
 Section 33 Township 6S Range 23E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
 4063' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well Plugged & Abandoned as follows:  
 Set CIBP @ 2930'  
 Set 45 sxs cement plug @ 2380-2930'  
 Set 10 sxs cement plug @ 1725-1825' to cover DV tool.  
 Set 10 sxs cement plug @ 1330-1430'  
 Perforate @ 900'  
 Set 60 sxs cement plug 650-900'  
 WOC & tag plug @ 668'  
 Set 10 sxs cement plug 110' to Surface  
 Displace casing w/mud between cement plugs  
 Installed dry hole marker

Pos - Prop



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tricia Moore TITLE Production Analyst DATE 01/24/2002

Type or print name Tricia Moore Telephone No. 505.623.4735

APPROVED BY [Signature] TITLE [Signature] DATE JAN 30 2002

Conditions of approval, if any: