
Energy, Minerals and Natural Resources  155 N. French De. Hobba. NM 85240  Johnsell  15 South French De. Hobba. NM 85240  Johnsell  16 South Pacheco  JON ON 155 First From NM 85240  JON ON 155 First French De. Hobba. NM 85240  JON ON			C150	
Energy, Minerals and Natural Resources   Energy, Minerals and Natural Resources   Section   Se		State of New Mexico	Form C-103	
OIL CONSERVATION DIVISION   2040 South Pacheco   South Pache	1/	, Minerals and Natural Resources	Revised March 25, 1999	
81 Sand First, Areals, MM 83210 Donne III DON ROS Brazes Rd, Azlee, NM 87410 SUNDEN NOTICES AND REPORTS ON WELLS SUNDEN NOTICES AND REPORTS ON WELLS DO NOT USE THIS DONN'THE PROPOSALS TO DRELL OR TO DEFEN OR PLUC BACK.  BUSINESS ON THE PROPOSALS TO DRELL OR TO DEFEN OR PLUC BACK.  DO NOT USE THIS DONN'THE PROPOSALS TO DRELL OR TO DEFEN OR PLUC BACK.  The PROPOSALS.  1. Type of Well: DI W	Nictrical II			
South Person Rd, Anter, NM 87405   South Person, Santa F. NM 87505   Sou	811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION			
Sample Name	1000 Rio Brazos Rd - Aztec NM 87410		\	
SUNDRY NOTICES AND REPORTS ON WELLS  OD NOTICES THIS PORM FOR PROPOSALS TO DRILL OR TO DEFEN OR PLUG BACK TO A DOMNSTEAST RESIDENCIA. USE 74/24CATON FOR THE MIGHT OF ORDER  PROPOSALS.  1. Type of Well.  Oil Well.  Oil Well.  Oil Well.  Oil Well.  Oil Well Cas Well   Other Injection  1. Address of Operator  Concho Oil & Gas Corp.  1. Well No.  Concho Oil & Gas Corp.  1. Well Louisians Ste 410; Midland, Tx 79701  4. Well Location  Unit Letter N: 990 Feet from the South line and 1650 feet from the West line  Section 7 Township 98 Range 29E NMPM Chaves County  10. Elevation (Show whether DR, RKB, RT, CR, etc.)  3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT   CREMENT JOBS   CREM	District IV Santa Fe, NM 8/505			
DONOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFERN OR PLUG BACK TO A DIFFERENT RESERVORE. USE "APPLICATION FOR PROMIT" ( ORNI C. 01) FOR SICH PROPOSALS, 1. Type of Well: Oil Well Gas Well Gother Injection Other Injection Oil Well Gas Corp. 2. Name of Operator Concho Oil & Gas Corp. 3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701 Twin Lakes; San Andres (Assoc) 4. Well Location Unit Letter N: 990 Feet from the South line and 1650 feet from the West line Section 7 Township 9S Range 29F NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 393.1.0 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMPLETION OTHER: COMPLETION COMPLETION CEMENT JOB OTHER: COMPLETION COMPLETION CEMENT JOB OTHER: COMPLETION COMPLETION CEMENT JOB OTHER: COMPLETION CEMENT JOB OTHER CEMENT JOB OTHER CEMENT JOB OTHER COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION				
RROPOSALS    1. Type of Well:   Other   Gas Well   Other	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL	7. Lease Name or Unit Agreement Name:		
1. Type of Well   Gas Well   Other injection   7. Well No.			Twin Lakes San Andres Unit	
2. Name of Oferator Concho Oil & Gas Corp.  3. Address of Operator 110 W. Louisiana Ste 410, Midland, Tx 79701  4. Well Location Unit Letter N: 990 Feet from the South line and 1650 feet from the West line Section 7 Township 98 Range 29E NMPM Chaves County 10. Elevation (Show whether DR. RKB, RT, GR. etc.) 3931.0 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   PULL OR ALTER CASING   MULTIPLE   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CHER:   OTHER:   OTHER:   OTHER:     OTHER:   OTHER:   OTHER:     OTH	1. Type of Well:			
Concho Oil & Gas Corp.   112		Injection		
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701  4. Well Location  Unit Letter N: 990 Feet from the South line and 1650 feet from the West line  Section 7 Township 98 Range 29E NMPM Chaves County  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT CEMENT 30B COMPLETION   CASING TEST AND CEMENT 30B CEMENT 30B COMPLETION   CASING TEST AND CEMENT 30B			†	
Unit Letter N: 990 Feet from the South line and 1650 feet from the West line  Section 7 Township 9S Range 29E NMPM Chaves County  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   ABANDONMENT   COMPLETION   CEMENT JOB   TOTHER:   OTHER:   OTHER:   TOTHER:   OTHER:   OTHER:   TOTHER:   OTHER:   TOTHER:				
Unit Letter N: 990 Feet from the South line and 1650 feet from the West line  Section 7 Township 9S Range 29E NMPM Chaves County  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLAGE AND ABANDON ALTER CASING COMMENCE DRILLING OPNS. ALTERING CASING COMMENT JOB  PULL OR ALTER CASING MULTIPLE COMPLETION CHANGE PLAGE ABANDONMENT  COMPLETION OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  Secribe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  Notify the NMOCD Artesia District 24 hours prior to commencement.  Set 125' cmt plug 2025-2750'. WOC & tag.  Circ hole w/ mad.  4.25 \$\sqrt{9}\$ Set \$\sqrt{1}\$ cmt plug 202080'.  Signa Perf 2000' & set 100' cmt plug 202080'.  Signa Perf 2000' & set 100' cmt plug 202080'.  Signa Perf 2000' & set 100' cmt plug 202080'.  Title Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  Title Production Analyst DATE 1-11-02  Type or print name Terri Stathem Title DATE  APPPROVED BY TITLE			Twin Lakes; San Andres (Assoc)	
Section 7 Township 0S Range 29E NMPM Chaves County  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS.  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  Notify the NMOCD Artesia District 24 hours prior to commencement.  Notify the NMOCD Artesia District 24 hours prior to commencement.  Set 125' cmp lug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25' Set 18' cmp lug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25' Set 18' cmp lug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25' Perf @ 100' & set 100' cmt plug @ 15-15-15-15-15-15-15-15-15-15-15-15-15-1	4. Well Location			
Section 7 Township 0S Range 29E NMPM Chaves County  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS.  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  Notify the NMOCD Artesia District 24 hours prior to commencement.  Notify the NMOCD Artesia District 24 hours prior to commencement.  Set 125' cmp lug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25' Set 18' cmp lug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25' Set 18' cmp lug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25' Perf @ 100' & set 100' cmt plug @ 15-15-15-15-15-15-15-15-15-15-15-15-15-1	Unit Letter N: 990 Feet from the	South line and 1650 fee	t from the West line	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3931.0 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT   PULL OR ALTER CASING   MULTIPLE   CASING TEST AND CEMENT JOB   OTHER:   OTHER:   OTHER:   OTHER:   OTHER:   OTHER:   OTHER:   OTHER:   12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement. 2. Set 125' cmt plug @ 2025-2750. WOC & tag. 3. Circ hole w/ mud.   2025-2750. WOC & tag. 3. Circ hole w/ mud.   2025-2750. WOC & tag. 4.25 Set im cmt plug @ 2025-2080'. 5.1500 Perf @ 100 cmt plug @ 100-2080'. 5.1500 Perf @ 100 cmt plug @ 100-2080'. 7.2016 Perf @ 100 cmt pl				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT   PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB   OTHER:   OTHER:   OTHER:    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement. 2. Set 125' cmt plug @ 2625-2750'. WOC & tag. 3. Circ hole w/ mud. 4,25 9'. Set 12' cmt plug @ 2625-2750'. WOC & tag. 5. ISCO Perf @ 16' & set 100' cmt plug @ 150-950'. 7. 21c' Perf @ 16' & set 100'				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER:   OTHER:   OTHER:    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement.  2. Set 125' cmt plug @ 2625-2750'. WOC & tag.  3. Circ hole w/ mud.  4.25' Set 12' cmt plug @ 100-2080'.  5.1500 Perf @ 100' & set 100' cmt plug @ 150-100'.  Figure 1 100' & set 100' cmt plug @ 150-100'.  Figure 1 100' & set 100' cmt plug @ 150-100'.  Type or print name   Terri Stathem   TITLE   Production Analyst   DATE   1-11-02    Type or print name   Terri Stathem   Terri Stathem   Telephone No. 915/683-7443    Title   DATE   DATE   DATE    Title   DATE   DATE   DATE    Title   DATE   DATE    Total Policy   DATE    Total Policy   DATE   DATE    Total Policy   DATE    To				
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND   CEMENT JOB    OTHER:   OTHER:   OTHER:   OTHER:    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement.  2. Set 125' cmt plug @ 2025-2750'. WOC & tag.  3. Circ hole w/mud.  4.25.9/ Set 12' cmt plug @ 30-2080'.  5.15co Perf @ 10' & set 100' cmt plug @ 150-950'.  7.216' Perf @ 300' & set 100' cmt plug @ 850-950'.  7.216' Perf @ 300' & set 100' cmt plug @ 850-950'.  7.216' Perf @ 300' & set 100' cmt plug @ 850-950'.  TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem. Telephone No. 915/683-7443  This space for State use)  APPPROVED BY				
TEMPORARILY ABANDON	NOTICE OF INTENTION	TO: \   SUE	-	
ABANDONMENT  ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  CASING TEST AND CEMENT JOB  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  CASING TEST AND  CEMENT JOB  OTHER:  OTHER:  CASING TEST AND  CEMENT JOB  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  OTHER:  OTHER:  COMPLETION  OTHER:  COMPLETION  OTHER:  OTHER:  OTHER:  OTHER:  COMPLETION  OTHER:  OTHER:	PERFORM REMEDIAL WORK PLUG AND	ABANDON 🔽 REMEDIAL WOF	K ALTERING CASING	
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement.  2. Set 125' cmt plug @ 2625-2750'. WOC & tag.  3. Circ hole w/ mud.  425-9/ Set 126' cmt plug @ 150-2080'.  5. ISCO Perf @ 160' & set 100' cmt plug @ 150-1500'.  7. 216' Perf @ 900' & set 100' cmt plug @ 150-1500'.  7. 216' Perf @ 900' & complete to the best of my knowledge and belief.  SIGNATURE  TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem  Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY  TITLE  DATE	TEMPORARILY ABANDON	_ANS		
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  Notify the NMOCD Artesia District 24 hours prior to commencement.  Set 125' cmt plug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25.49 Set 120' cmt plug @ 100.2080'.  S. 1500 Perf @ 16 & set 100' cmt plug @ 150.2080'.  S. 1500 Perf @ 16 & set 100' cmt plug @ 150.2080'.  Cut off wellhead & install P&A marker.  I hereby certify that the information above is trace and complete to the best of my knowledge and belief.  SIGNATURE  TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem TITLE DATE  DATE	PULL OR ALTER CASING   MULTIPLE	☐ CASING TEST A		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  Notify the NMOCD Artesia District 24 hours prior to commencement.  Set 125' cmt plug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  425.9' Set 182' cmt plug @ 100' 2080'.  5.1500 Perf @ 100' & set 100' cmt plug @ 850-950'.  7.316' Perf @ 100' & set 100' cmt plug @ 850-950'.  7.316' Perf @ 100' & set 100' cmt plug @ 850-950'.  Title Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)	COMPLETION	ON CEMENT JOB	_	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  Notify the NMOCD Artesia District 24 hours prior to commencement.  Set 125' cmt plug @ 2625-2750'. WOC & tag.  Circ hole w/ mud.  4.25  Set 125' cmt plug @ 120-2080'.  S. // Cor Perf @ 165' & set 100' cmt plug @ 150-165'.  Perf @ 900' & set 100' cmt plug @ 850-950'.  Perf @ 166'. Circ cmt from 216' to surface.  Cut off wellhead & install P&A marker.  I hereby certify that the information above is trae and complete to the best of my knowledge and belief.  SIGNATURE  TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem  Telephone No. 915/683-7443  (This space for State use)	OTHER:	OTHER:		
Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement.  2. Set 125' cmt plug @ 2625-2750'. WOC & tag.  3. Circ hole w/ mud.  4.25 Set   100' cmt plug @ 100-2080'.  5. 150 Perf @ 100' & set 100' cmt plug @ 150-100'.  6. Perf @ 900' & set 100' cmt plug @ 850-950'.  7. 16' Perf @ 10'. Circ cmt from 216' to surface.  8. Cut off wellhead & install P&A marker.  I hereby certify that the internation above is trievand complete to the best of my knowledge and belief.  SIGNATURE  TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY  TITLE  DATE	12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:  1. Notify the NMOCD Artesia District 24 hours prior to commencement.  2. Set 125' cmt plug @ 2625-2750'. WOC & tag.  3. Circ hole w/ mud.  4.25 9/ Set   Circ mode   Continued   Co				
1. Notify the NMOCD Artesia District 24 hours prior to commencement.  2. Set 125' cmt plug @ 2625-2750'. WOC & tag.  3. Circ hole w/ mud.  4.25 \$\frac{4}{2}\$ Set 12' cmt plug @ \( \text{2} \) \(	or recompliation.			
2. Set 125' cmt plug @ 2625-2750'. WOC & tag.  3. Circ hole w/ mud.  4.25 # Set 12' cmt plug @ 120-2080'.  5.1500 Perf @ 165' & set 100' cmt plug @ 150-150'.  6. Perf @ 900' & set 100' cmt plug @ 850-950'.  7.216' Perf @ 125'. Circ cmt from 216' to surface.  8. Cut off wellhead & install P&A marker.  I hereby certify that the information above is trae and complete to the best of my knowledge and belief.  SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE				
3. Circ hole w/ mud. 4.25 \$\frac{1}{2}\$ Set 1 \$\frac{1}{2}\$ ' cmt plug @ 150-2080'. 5.1500 Perf @ 1 \$\frac{1}{2}\$ ' & set 100' cmt plug @ 150-950'. 6. Perf @ 900' & set 100' cmt plug @ 850-950'. 7.216' Perf @ 150'. Circ cmt from 216' to surface. 8. Cut off wellhead & install P&A marker.  I hereby certify that the information above is trie and complete to the best of my knowledge and belief.  SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE				
4.25 Set 1 cmt plug @ 20.2080'.  5.15 Perf @ 165' & set 100' cmt plug @ 15.15 co'.  6. Perf @ 900' & set 100' cmt plug @ 850-950'.  7.216' Perf @ 166'. Circ cmt from 216' to surface.  8. Cut off wellhead & install P&A marker.  I hereby certify that the information above is trag and complete to the best of my knowledge and belief.  SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE  DATE		& tag.		
6. Perf @ 900' & set 100' cmt plug @ 850-950'.  7 216' Perf @ 126'. Circ cmt from 216' to surface.  8. Cut off wellhead & install P&A marker.  I hereby certify that the information above is trie and complete to the best of my knowledge and belief.  SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE	4.25 <b>9</b> Set 1 cmt plug @ 10-2080'.			
Perf @ ***. Circ cmt from 216' to surface.  8. Cut off wellhead & install P&A marker.  I hereby certify that the information above is trae and complete to the best of my knowledge and belief.  SIGNATURE  TITLE ** Production Analyst** DATE ** 1-11-02**  Type or print name ** Terri Stathem ** Telephone No. 915/683-7443*  (This space for State use)  APPPROVED BY ** TITLE ** DATE **	5./5∞ Perf @ 1 € 8 set 100' cmt plug @ 1€	1,1405 1500	100	
8. Cut off wellhead & install P&A marker.  I hereby certify that the information above is trie and complete to the best of my knowledge and belief.  SIGNATURE  TITLE Production Analyst  DATE 1-11-02  Type or print name  Terri Stathem  Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY  TITLE  DATE				
SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE		acc.		
SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE				
SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE				
SIGNATURE TITLE Production Analyst DATE 1-11-02  Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE DATE	I hereby certify that the information above is true and complete to the best of my knowledge and belief			
Type or print name Terri Stathem Telephone No. 915/683-7443  (This space for State use)  APPPROVED BY TITLE		Les	ge und better.	
(This space for State use)  APPPROVED BY	SIGNATURE JAM.	TITLE <u>Production Ana</u>	lyst DATE 1-11-02	
(This space for State use)  APPPROVED BY	Type or print name Terri Stathem Telephone No. 915/683-7443			
APPPROVED BY TITLE DATE  Conditions of approval if any:	7 3 F 17 \	11 -11 11	1 . 70	
APPPROVED BY TITLE DATE	A PARTA OVER DV	suld to	the second	
Conditions of approval, if any.	Conditions of approval, if any:	HILE	N DATE	

## TLSAU #112

## Formerly - Moonshine 7 #8



Original Perf Details: P1: 2675, 76, 85, 86, 90, 91, 92, 2701, 02, 03, 04

5000 gals 20% acid

Apr-90 Add P1: 2682, 85.5, 97, 2709, 16, 22, 24, 26

No treatment