

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 21493

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Vance Federal "A"

9. WELL NO.

1

10. FIELD AND BOO, OR WILDCAT

Sec. 34, 7S, 26E

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, 7S, 26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3768 GR

12. COUNTY OR PARISH

Chaves

13. STATE

New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

5-9-82 Drld. 12 1/4" hole to 920'. Ran 23 jrs. 8 5/8" 24 & 32# J-55 csg. set @ 918' Cmt. w/360 sx. Howco Lite w/5# Gilsomite & 1/4# flocele per sx. Followed w/200 sx. Class "C" w/2% CaCl. Plug down @ 9:00 pm. Circ. 60 sx. WOC. Tested pipe & BOP @ 1000# for 30 min.. Tested OK.

5-17-82 Drld. 7 7/8" hole to TD. 4555'. Ran logs.

5-18-82 Ran 113 jts. 4 1/2" 10.50# J-55 csg. set @ 4555'. Cmt. w/100 sx. Howco Lite w/5# KCL & 1/4# flocele per sx. Followed w/350 sx. 50-50 Pozmix w/.03 of 1% Halid 4, .02 of 1% CFR-2 and 3# KCL per sx. Plug down @ 10:30 am. Top cmt. 3400'. Cmt. second stage, opened DV Collar & cmt. w/450 sx. 50-50 Pozmix w/6# salt per sx. Plug down @ 3:00 pm. Top cmt. 1000'. Released rig. Tested pipe & BOP @ 1000# for 30 min.. Tested OK.

5-28-82 Ran 3 7/8" bit & drld. out to 4533'; PBTD.

6-1-82 Perf. .40" holes 1/SPF @ 4085-89, 4321', 22, 24, 3032', 33, 4344', 45, 46, 48, 51, (2)holes @ 4352', (1) @ 56', (2) @ 57', (1) @ 58', (2) @ 4396', (1) @ 4397', 98', 4485', 86', (2) @ 4487', (1) @ 4488', 92', 96', 4501', (2) @ 4502', 07, 08, . Total 45 holes. Acidized w/1800 gals. acid.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Denney R. L. Denney

TITLE Chief Production Clerk

DATE 6-3-82

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

OCT 15 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.