· · · · · · · · · · · · · · · · · · ·	CONS. CONDIISSION O STATES SUBMIT IN TRIPLI	CATE - Form approved.
NIM OLL	DD DEPAR JF THE INTERIOR (Other Instructi	
May 1963) Drawer <u>Artesi</u>		5. LEASE DESIGNATION AND SERIAL NO.
Artesi		NM-16783
	SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not ut	e this form for proposals to drill or to deepen or pl	
	int reservoir. Use "APPLICA <b>REGENVEP</b> ERMIT-" for such	
		7. UNIT AGREEMENT NAME
• • · · · · · · · · · · · · · · · · · ·	L X OTHER	
++	OCT 1 5/1987	
. NAME OF OPERATOR		8. FARM OR LEASE NAME
Read & Stevens,	$\mathbf{U}$	Beard Federal 1-
ADDRESS OF OPERAT	APTECIA Othersold I ( 1987	9. WELL NO.
P.0. Box 1518,	Roswell, NM 88201	
	Report location clearly and in accordance with State $\operatorname{Oil} \& \operatorname{GAS}$	10. FIELD AND POOL, OR WILDCAT
•	ee also space 17 below.) U.S. GEOLOGICAL SUR	
At surface	ROSWELL, NEW MEXI	
660'	FSL & 660' FWL	SURVEY OR AREA
14, PERMIT NO.	15. ELEVATIONS(Show whether DF,RT,GR,	
	37741 GR	Chaves New Mexico
6.	Check Appropriate Box To Indicate Nature of Notice,	, Report, Other Data
N	DTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-	DEF PULL OR ALTER CASING WATER	R SHUT-OFF REPAIRING WELL
		TURE TREATMENT ALTERING CASING
EDACTINE TREAT		
FRACTURE TREAT	#	IING UK AGIDIZING I I ABANDUNMENI^ I I
SHOOT OR ACIDIZE	ABANDON* SHOO	TING OR ACIDIZING ABANDONMENT*
SHOOT OR ACIDIZE REPAIR WELL	ABANDON* SHOO CHANGE PLANS (Othe	er) Spud, csg, cmt & test X
SHOOT OR ACIDIZE REPAIR WELL (Other)	ABANDON* SHOO CHANGE PLANS (Othe (NO Con	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.)
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of	ABANDON* SHOO CHANGE PLANS (Other (NO	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)*
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally depths for all markers and zones pertinent to this	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)*
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally I depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally I depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drlg Co. Start drlg w/Sierra Rotary Rig #5 @ 9:00am 10-3-82	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally l depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well <u>mpletion or Recompletion Report and Log form.</u> ) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally I depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2\$ CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2\$ CaCl <sub>2</sub> .	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally I depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2\$ CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2\$ CaCl <sub>2</sub> .	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well <u>mpletion or Recompletion Report and Log form.</u> ) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82	ABANDON* CHANGE PLANS CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally I depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drlg Co. Start drlg w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl2, tail-in w/250sx Class "C" w/2% CaCl2. I 75sx, witnessed by USMMS, float held.	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well <u>mpletion or Recompletion Report and Log form.</u> ) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-5-82 10-6-82	ABANDON* CHANGE PLANS CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally I depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drlg Co. Start drlg w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl2, tail-in w/250sx Class "C" w/2% CaCl2. I 75sx, witnessed by USMMS, float held.	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well <u>mpletion or Recompletion Report and Log form.</u> ) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-5-82 10-6-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/A w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . I 75sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well <u>mpletion or Recompletion Report and Log form.</u> ) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-5-82 10-6-82	ABANDON* CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/A w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . I 75sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82 10-6-82	ABANDON* CHANGE PLANS CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w. Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . T5sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa hat the foregoing is true and correct TITLE Drilling & Pro-	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82 10-6-82 10-6-82 10-6-82	ABANDON* CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally f depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drlg Co. Start drlg w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . I 75sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa hat the foregoing is true and correct TITLE Drilling & Pro	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82 10-5-82 10-6-82	ABANDON* CHANGE PLANS CHANGE PLANS O OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w. Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . T5sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa hat the foregoing is true and correct TITLE Drilling & Pro-	er) <u>Spud, csg, cmt &amp; test</u> X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82 10-5-82 10-6-82	ABANDON* CHANGE PLANS OR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . T5sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa hat the foregoing is true and correct TITLE Drilling & Pro DRIG. SGD.) DAVID R. GLASS TITLE	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82 10-5-82 10-6-82 10-6-82 (This space for APPROVED BY CONDITIONS OF AF	ABANDON* CHANGE PLANS O CR COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2\$ CaCl2, tail-in w/250sx Class "C" w/2\$ CaCl2. I 75sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa hat the foregoing is true and correct TITLE Drilling & Pro PROVAL, IF ANY: OCT 1 4 1982	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.
SHOOT OR ACIDIZE REPAIR WELL (Other) 7.DESCRIBE PROPOSE estimated date of and true vertica 9-25-82 10-1-82 10-3-82 10-5-82 10-5-82 10-6-82 10-6-82 (This space for APPROVED BY CONDITIONS OF AF	ABANDON* CHANGE PLANS CHANGE PLANS COMPLETED OPERATIONS (Clearly state all pertinent f starting any proposed work. If well is directionally i depths for all markers and zones pertinent to this Build location. Set 41', 16" conductor pipe, cmt w Spud @ 8:00am 9-30-82 w/Collins Drig Co. Start drig w/Sierra Rotary Rig #5 @ 9:00am 10-3-82 TD 14 3/4" hole @ 10:30pm 10-4-82 @ 900'. Set 22jt & 45.5#, J-55 ST&C, set @ 900', FC @ 860'. Cmt w/4 w/2% CaCl <sub>2</sub> , tail-in w/250sx Class "C" w/2% CaCl <sub>2</sub> . T5sx, witnessed by USMMS, float held. 18hrs WOC. Test csg @ 1000psi for 30min, tested sa hat the foregoing is true and correct TILE Drilling & Pro PROVAL. IF ANY:	er) Spud, csg, cmt & test X TE:Report results of multiple completion on Well mpletion or Recompletion Report and Log form.) details, and give pertinent dates, including y drilled give subsurface locations and measured work.)* /6 yds Redi-Mix.