TATES NM OSTERCONS: 1 MESSEON THE INTERIOR WORLD DISTRICTIONS ON THE 1 UNITED STATES

Form approved.
Budget Bureau No. 42 R1424.
DESIGNATION AND SERIAL NO.

| | GEOLOGICAL SURVEY | Artesia, NM 88210 | NM 17036 |
|---|--|--|--|
| SUNE (Do not use this fo | DRY NOTICES AND REPORTS orm for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such | ON WELLS back to a different reservoir. proposals.) | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| 1. OH. CVI GAS [| · . | | 7. UNIT AGREEMENT NAME |
| WELL NELL | OTHER | | S. FARM OR LEASE NAME |
| 2. NAME OF OPERATOR | FELOPMENT CORPORATION (.) | JUN atting to | Wolf Federal |
| 3. ADDRESS OF OPERATOR | - Caral | 11 | 9. WELL NO. |
| | laria, N.E., Albuquerqu è, NM | | #] 10. FIELD AND POOL, OR WILDCAT |
| See also space 17 belov | port location clearly and in accordance with an | y State requirements. | Wildcat $-S/2$ |
| At surface | | | 11. SEC., T., R., M., OR BLK. AND |
| 2,08 | BO' FSL, 330' FWL | | SURVEY OR AREA |
| | | | Sec. 25, T4S, R25E |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether) | of, RT, GE, etc.) | 12. COUNTY OR PARISH 13. STATE |
| | 3755.11' GL | | Chaves NM |
| 1ψ. | Check Appropriate Box To Indicate | Nature of Notice, Report, or (| Other Data |
| S | UTICE OF INTENTION TO: | SUBSEQ | UENT REPORT OF: |
| TEST WATER SHUT-OF | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WELL |
| FRACTURE TREAT | MULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING CASING |
| SHOOT OR ACIDIZE | ABANDON* | SHOOTING OR ACIDIZING | ABANDON MENT* |
| REPAIR WELL | CHANGE PLANS | (Other)(Note: Report result | s of multiple completion on Well pletion Report and Log form.) |
| (Other) 17. DESCRIBE PROPOSED OR proposed work. If nent to this work.) | COMPLETED OPERATIONS (Clearly state all pertinuell is directionally drilled, give subsurface locally drilled, give subsurface locall | 4 3 4 13 7 1 - months and dates | including estimated date of starting any |
| It is Propos | ed To: | | |
| Set a 3 | O sx cement plug from 3750' | - 3650' (tag plug to | find top) |
| Set a 3 | O sx cement plug from 1660' | - 1560' (tag plug to | |
| | 0 sx cement plug from 1060' | | find top) |
| Set a 2 | 0 sx cement plug from 50' | - Sfc. | _ |
| Install | Dryhole Marker | | |
| | | RE | ECEIVED BY |
| | | | |
| | | j Jl | JN 19 1984 |
| | | | O. C. D. |
| | | AF | RTESIA, OFFICE |
| | | No. of the latest states and the latest stat | The State of the State of the Association and State of St |
| | | | |
| | | | |
| 18. I hereby certify that | the foregoing is true and correct | | |
| SIGNED LIME | TITLE _ | Field Mapager | DATE June 13, 1984 |

ACCEPTED FOR RECORD

| APPROVED BY CONDITIONS OF APPROVAL, IF LAY 984 | (Oir Bad) PETER W. CHESTER UN 1 8 1984 | DATE |
|--|--|------|
| | *See Instructions on Reverse Line | |