

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135
Expires August 31, 1985

9102
NM 88210
Artesia, NM 88210

5. LEASE DESIGNATION AND SERIAL NO.
NM 17417

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Petroleum Development Corporation *TS/ER Exploration Inc.*

3. ADDRESS OF OPERATOR

9720 B Candelaria, NE Albuquerque, NM 87112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

660' FNL, 660' FWL

U.D.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Barbara Ann Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Undes, ABO

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 7, T7S, R27E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3883' GL 3895' KB

12. COUNTY OR PARISH

13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Set cast iron BP @ 4687'.
2. Displace hole w/9.0# gelmud from 4687' to surface.
3. Spot 10 sx cement plug from 4687' - 4563'.
4. Spot 15 sx cement plug from 3776' - 3592'.
5. Spot 10 sx cement plug from 917' - 794'.
6. Spot 10 sx cement plug from 398' - 275'.
7. Set 10 sx cement plug from 138' - surface.
8. Install dry hole marker, completed P&A job @2:30 pm on May 10, 1995.

*Part ID-2
6-9-95
P&A*

RECEIVED

MAY 25 1995

OIL CON. DIV.
DIST. 2

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Vice President

DATE

5-12-95

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
DATE 5-12-95
MAY 23 1995
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE CENTER

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

Budget Bureau No. 1004-0155
Expires August 31, 1985

NON PERMITTING STATES
(Other Instructions)

5. LEASE DESIGNATION AND SERIAL NO.
NM 17417

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Barbara Ann Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Undes, ABO

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 7, T7S, R27E

12. COUNTY OR PARISH 13. STATE

OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Petroleum Development Corporation *ISKR Explorations Inc*

3. ADDRESS OF OPERATOR

9720 B Candelaria, NE Albuquerque, NM 87112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL, 660' FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3883' GL 3895' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set cast iron BP @ 4687'.
2. Displace hole w/9.0# gelmud from 4687' to surface.
3. Spot 10 sx cement plug from 4687' - 4563'.
4. Spot 15 sx cement plug from 3776' - 3592'.
5. Spot 10 sx cement plug from 917' - 794'.
6. Spot 10 sx cement plug from 398' - 275'.
7. Set 10 sx cement plug from 138' - surface.
8. Install dry hole marker, completed P&A job @2:30 pm on May 10, 1995.

RECEIVED

MAY 25 1995

OIL CON. DIV.
DIST. 2

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE Vice President

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

DATE 5-12-95

APPROVED
PETER W. CHESTER
DATE

MAY 23 1995

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side