

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED

APR 19 1983

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

O. C. D.

ARTESIA, OFFICE

OIL WELL ☐ GAS WELL ☐ OTHER- Plug & Abandon

Name of Operator
STEVENS OPERATING CORPORATION ✓

Address of Operator
P. O. Box 2408, Roswell, NM 88201

Location of Well
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 16 TOWNSHIP 7S RANGE 27E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4047 GL

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name RUA STATE
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat San Andres
12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

18. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-14-83 Ran 76 joints 2 3/8" x 4.7# tubing. Set at 2036'. Circulated hole w/gel water & follow w/100 sxs Class "C" cement w.4% CaCl₂. Pulled up, WOC 2 hrs. & tag 1st plug at 1795' (242' fill). Pulled 24 joints & set cement plug at 1395' to 1282' using 50 sxs Class "C" cement w/4% CaCl₂. Pulled 34 joints, set 50 sxs. plug at 482' to 376' & pulled out w/tubing. Ran 1 joint back in & circ 10 sxs to surface.

Post ID-2
4-22-83
DTH

19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Controller DATE April 18, 1983
APPROVED BY [Signature] TITLE Geologist DATE 10/6/83
CONDITIONS OF APPROVAL, IF ANY: