		NM OIL CONS.	COMMIS	NOIS	9SF
Form 9–331 Dec. 1973		Drawer DD Artesia, NN	99910		Approved.
Dec. 1973	UNITED STATE		OCELV	5. LEASE	t Bureau No. 42–R1424
DE	PARTMENT OF THE	INTERIOR		NM-19582	
GEOLOGICAL SURVEY			6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)				7. UNIT AGREEMENT NA	
1. oilg	as			8. FARM OR LEASE NAM Gragg <del>Fed.</del> "A"	F. JAN 16 1984
well well other Dry 2. NAME OF OPERATOR /				9. WELL NO.	O. C. D.
McClellan Oil Corporation				10. FIELD OR WILDCAT N	ARTESIA, OFFICE
3. ADDRESS OF OPERATOR				Wildcat - 1926	con lo
P.O. Drawer 730, Roswell, N.M.				11. SEC., T., R., M., OR B AREA	LK. AND SURVEY OR
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> </ol>				Sec. 24-T14S-R2	22E
AT SURFACE: 760' FSL & 660' FW				12. COUNTY OR PARISH	13. STATE
AT TOP PROD AT TOTAL DEP				Chaves	N.M.
16. CHECK APPRO	PRIATE BOX TO INDIC	ATE NATURE OF	NOTICE	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			15. ELEVATIONS (SHOW		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF			3975' G.L.	DI, KUB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:					
FRACTURE TREAT $\Box$ $\Box$ $D$ $F(C E V E)$					
SHOOT OR ACIDIZ REPAIR WELL					
PULL OR ALTER C				(NOTE: Report results of mul change on Form 9-3	tiple completion or zone 30.)
MULTIPLE COMPLE CHANGE ZONES			MAY	4 1983	
ABANDON*	$\overline{\mathbf{x}}$	L.	OM.	PAS	
(other)		<del></del>		_ •	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*					
4-21-83:	Perfed 4929-38'. Swabbed dry. Se	Acidized w t CIBP at 4	ith 100 920'.	00 gals. 7½% Spearh	ead.
4-25-83:	Perfed 4857-4908	'. Acidized	with 2	2000 gals. 10% Spea	rhead. Swabbed dry.
4-28-83: Plugged & Abandoned as follows:					
1. Set 35 sx Class "C" plug from 4750'-4920'					
<ol> <li>Pulled 4½" casing from 3770' to surface. Circulated hole with salt mud.</li> </ol>					
		ug from 3700	' to 10	1501	
<ol> <li>Set 40 sx plug from 3700' to 4050'.</li> <li>Set 80 sx Class "C" w/4% CaCl<sub>2</sub> plug from 800' to 1160'. Wait</li> </ol>					
	4 nours and	tag jul.			
Subsurface Safety	5. Set 40 sx C1 Valve: Manu. and Type	ass "C" plug	from 6	0' to surface. In Set@	stall dry hole marke ⊇Ft.
18. I hereby certify that the foregoing is true and correct					
SIGNED Find TITLE Operations Manager DATE May 2, 1983					
APPROVED (This space for Federal or State office use)					
APPROVED BY DATE DATE DATE					
NOTE: Will clean and level location after pits dry.					
•See Instructions on Reverse Side					