

Submit 3 Copies
To Appropriate
District Office
DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
811 South First, Artesia NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised 1-1-89

WELL API NO.

30-005-62055

17. Indicate Type of Lease

STATE - ☒ FEE ☐

18. State Oil & Gas Lease No.

VA—1047

19. Lease Name or Unit Agreement
Name:

West Elida Unit

16. Well No.

1

17. Pool name or Wildcat

Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-106) FOR SUCH
PROPOSALS)

17. Type of Well:

Oil Well ☐

Gas Well ☒

Other ☐

18. Name of Operator

Prairie Sun, Inc.

19. Address of Operator

P. O. Box 8280 Roswell, NM 88202—8280

20. Well Location

Unit letter C : 660 feet from the North line and 1980 feet from the West line

14. Elevation (Show whether DF, RKB, RT, GR, etc.)
4726' GR

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

REMEDIAL WORK

()

PLUG AND ABANDON

()

REMEDIAL WORK

()

SUBSEQUENT REPORT OF:

ALTERING CASING

()

TEMPORARILY ABANDON

()

CHANGE PLANS

()

COMMENCE DRILLING OPNS.

()

PLUG & ABAND.

()

PULL OR ALTER CASING

()

CASING TEST AND CEMENT JOB

OTHER:

OTHER: Continued Operations

16. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

12-13-98 thru 12-15-98

Move in and rig up Ram Well Service pulling unit. Move in and rig up reverse equipment. Make up 7 7/8" bit, 8—4.75" drill collars and go in hole. Pick up tubing and tag at 2780'. Pick up swivel and drill cement to 2798' on some kind of junk. Circulate hole with clean water. Pull out of hole and make up magnet. TIH w/ magnet and fish junk. POH and recovered 2 pieces of flat iron 1.5" wide & 2" long. Go in hole with drill collars. Lay down drill collars. Rig down and release pulling unit and the rental equipment on 12-15-98. Well shut in with BOP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE Agent DATE 12-20-98

Type or print name Gene Lee

Telephone No. 505-622-7355

(This space for State use)

APPROVED

BY

Jim W. Gumb

TITLE

District Supervisor

DATE

1-14-99

Conditions of approval, if any: