

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.  
30-005-62055

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
VA- 1047

7. Lease Name or Unit Agreement Name:

West Elida

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Prairie Sun, Inc.

8. Well No.

1

3. Address of Operator  
P.O. Box 8280 Roswell, NM 88202-8280

9. Pool name or Wildcat  
Wildcat

4. Well Location

Unit Letter C : 660 feet from the North line and 1980 feet from the West line

Section 14 Township 4S Range 29E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4721 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Operator proposes to P&A well as follows:

Plug #1: Top Penn. CIBP @ 7700'. Cement on top of CIBP from 7300--7700'.

Circulate hole with 25#/bbl salt gel mud.

Plug #2: Top Wolfcamp 6730'--6830' w/ 15 sx. Class "H" - min 25 sx plug

Plug #3: Top Abo 6000'--6100' w/ 15 sx. Class "H" - min 25 sx plug

Cut 4.5" csg at 5700'.

Plug #4: Casing stub 5600'--5800' w/ 35 sx. Class "H" Tag Plug.

Plug #5: Top Glorieta 3850'--3950' w/ 25 sx. Class "H"

Plug #6: 8 5/8 shoe 2600'--2800' w/ 35 sx. Class "H" Tag Plug. 100' plug 1615-1715

Plug #7: 600-800' 800-1000' w/ 35 sx. Class "H" Tag Plug.

Submit affidavit of responsibility for surface owner to keep wellbore for domestic water well.

Cut off anchors, level location, fill cellar, reclaim and reseed surface with proper grass mixture.

OCD approval pending receipt of affidavit for water well  
If surface plug is set - min is 0-60' inside & outside all casing strings

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE Agent DATE 9/18/02

Type or print name Gene Lee Telephone No. 626-4292

(This space for State use)

APPROVED BY [Signature] TITLE Compliance Officer DATE 9/24/02

Conditions of approval, if any:

Receipt of affidavit for water well or surface plug to be set.