

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501  
RECEIVED BY  
JAN 05 1984  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐  
Name of Operator  
Stevens Operating Corporation  
Address of Operator  
P. O. Box 2408, Roswell, New Mexico 88201  
Location of Well  
UNIT LETTER F 2310 FEET FROM THE North LINE AND 2310 FEET FROM  
THE West LINE, SECTION 25 TOWNSHIP 8S RANGE 28E NMPM.  
15. Elevation (Show whether DF, RT, GR, etc.)  
3930.2 GR  
7. Unit Agreement Name  
8. Farm or Lease Name  
O'Brien "F"  
9. Well No.  
9  
10. Field and Pool, or Wildcat  
Twin Lakes San Andres  
12. County  
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Spud, Surface and Production Casing</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Desert Rig #1 rig up and spud @ 2:45 p.m. 12-20-83 with 12 1/4" Bit. Ran 3 joints 8 5/8" X 24# casing, set and cement @ 127' w/120 sxs Class "C" w/2% cc. Plug down @ 7:45 p.m. circ. 25 sxs. WOC 18 hours. Pressure up 1000# for 30 minutes logging no pressure decrease.

Ran 65 joints 4 1/2" X 11.6# casing, set and cement @ 2691' w/200 sxs 50/50 poz class "C" w/5# salt, 3/10 Halad-4. Plug down @ 3:00 p.m. 12-24-83. WOC 18 hours. Pressure up 1000# for 30 minutes logging, no pressure decrease.

10. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie A. Clements TITLE Production Controller DATE 12-29-83  
Original Signed By  
Leslie A. Clements  
Supervisor District II  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JAN 05 1984

CONDITIONS OF APPROVAL, IF ANY: