## STATE OF NEW MEXICO

WERGY .	ANN A	<b>ภเท</b> ียกกเร	DEPARTN	1FNT

wy. ## (4+165 %(CT1VEB	1	
DISTRIBUTION		
BANTA FE	1	
FILE	7	
U.S.G.S.		
LAND OFFICE		<u></u>
OPENATOR	7	

45. 47 CONSERVATION DIVISION	- A 144	
DISTRIBUTION P. O. BOX 2088	Form C-103 Revised 19-1-78	
SANTA FE, NEW MEXICO 87501	•	
TILE	5a, Indicate Type of Lease	
U,\$.0.\$.	State Fee X	
LAND OFFICE	5. State Oil & Gas Lease No.	
OPENATOR		
	mmmmm <del>k</del>	
SUNDRY NOTICES AND REPORTS ON WELLS		
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name	
01L	7. Ollit Adreement (Value	
WELL X OTHER-		
Nume of Operator	8. Farm or Lease Name	
STEVENS OPERATING CORPORATION	McKnight	
Address of Operator	9. Well No.	
P. O. Box 2408, Roswell, New Mexico	4	
Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER P 990 FEET FROM THE SOUTH LINE AND 660 FEET F	Pecos Slope Abo	
UNIT LETTER		
Foot 25 60 27F		
THE East LINE, SECTION 35 TOWNSHIP 6S RANGE 22E HA		
15. Elevation (Show whether DF, RT, GR, etc.)	12, County	
	Chaves ()	
4102.4 GR		
Check Appropriate Box To Indicate Nature of Notice, Report or		
NOTICE OF INTENTION TO: SUBSEQU	ENT REPORT OF:	
FREDRAM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
CHANGE PLANS CASING TEST AND CEMENT JOB		
OTHER		
OTHER		
. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu	ding estimated date of starting any proposed	
work) SEE RULE 1103.		
Plug & abandon hole, set 1st plug @ 2700 to 2600, used 35 sxs cemen		
used 35 sxs cement. 3rd plug @ 1346 to 1246, used 45 sxs cement.	Plug @ surface. Rig	
released @ 4:00 p.m. 1-4-84.	A Company of the Comp	
·		
TD 3141	•	
•	A	
	. +0-/	
·	Past 10-24	
	1/2 27-1	
	1 Cyt	
	<b>f</b> "	
I haveby could that the information above is true and complete to the best of my knowledge and belief.		