Submit 3 Copies To Appropriate District	State of New Mexico			00	Form C-103
Office District I	Energy, Minerals and Natural Resources			WELL API NO.	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONCEDIVATION DIVISION			30-005-62091	
811 South First, Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of	of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505				X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	54114 1 6, 111.1 6 / 5 65			6. State Oil & Gas Lease No.  LH-1898	
87505 SUNDRY NOTICES AND REPORTS ON WELLS				l	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					
PROPOSALS.)	E AFFEICATION FOR FERMIT (FORM C-101) FOR SUCH			Grynberg Stat	e Com
1. Type of Well: Oil Well Gas Well X	[ell: Gas Well X Other				
2. Name of Operator 7. Well No.					
Yates Petroleum Corporation #1					
3. Address of Operator 8. Pool name or Wildcat					
105 S. 4 <sup>th</sup> Street Artesia, NM 88210 OCO Pecos Slope Abo					
4. Well Location					
Unit Letter L: 198	30 feet from the S	South	line and 660	feet from the <b>V</b>	/est line
Ome Better	reet from the		mic und		inc
Section 20	Township 9S			IPM Chave	<b>S</b> County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  3812' GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOR		к 🗌	ALTERING CASING X	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB		
OTHER:			OTHER: Attempt	t Recompletion	X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of					
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 9/11/01 – Move in and rig up pulling unit.					
9/13/01 – Drilled out CIBP's at 4756', 4780' and 4783'. Continue in hole and tag at 5545'.					
9/14/01 – Set cement retainer at 5380'. Squeeze Wolfcamp perfs 5414-5429' with 100 sxs H + .4% FL and 50 sxs H					
neat. Squeeze off at 3000 psi.					
9/17/01 – Drill out retainer and cement at 5380'. Drill out CIBP at 5540'. Tag up at 6319'. 9/19/01 – TIH with CBL. TOC 3600'. Perforate Penn 6315-6330', 90 holes, .42" and re-perforate Penn 6163-6170'					
and 6190-6207' with 96 holes, .42".					
9/20/01 – Acidize perfs 6315-6330' with 1500 gals 7.5% IC HCL and perfs 6163-6207' with 2400 gals 7.5% IC HCL.					
9/27/01 – Set CIBP at 6295', capped with 35' of cement.					
TIH with 2-3/8" tbg and SN. Bottom of tubing 4726'.					
9/28/01 – Release all equipment. Well is \$1.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE MAIN [hpm title <u>Engineering Technician</u> DATE <u>January 7, 2002</u>					
Type or print name Susan Herpin Telephone No. 505-748-1471					
(This space for Sta					DATE AN 1 4 200
APPPROVED BY		_			_DATE
Conditions of app FOR RECOR	RD ONLY				