

Memo

From

LES CLEMENTS

District Supervisor

To

305' Pipe to -
brok Cc - out side of Conductor
Pipe - 550 SY - Cc 5081
Cmt in Conductor -

2000' 13 3/8' -
Will set - 8 5/8"

do not go over 450' - before
setting 8 5/8" -

Memo

From
LES CLEMENTS
District Supervisor

To 2-14-84

TD APPX 900' $\pm$ 749'

have set conductor pipe - in
process of drilling well when ground
began to cave in -

this location is west side of Pecos
River - ~~on~~ 100 yds $\pm$ - no collar
visible -

18"-20" conductor pipe apparently they
did not cut in - Area around well
is caving in & rig is in danger of
falling in hole is appx 10'

Accross & B.W. does not know
how deep ~~well~~ hole is -

additional cracks. 2 to 6' from
wash out - or well bore

Company man was to come in
tonight (14th - Am. 15th)

Oil Conservation Division Artesia

tie off rig & might attempt to
cut ~~with~~ csg at 740 $\pm$