

STAR TOOL COMPANY

Hobbs, N.M. • 505-397-1535
Brownfield, TX. • 806-637-6444
Roswell, N.M. • 505-623-9397

Plugs to be set as follows
CIBP @ 2250 w/ 38' amt.
on top

1) 100 plug 50' in/out 5A
▼ @ 1728 - 1628

2.) 100' plug from 1203 1103'
50' in/out ~~5A~~ @ 1103'

3.) Shoe of son. @ 368.
Toc on 4 1/2 500
cut off stub @ 500' spot
plug @ 550' to 318' & tag
covers stub & shoe.

4.) Run 1 1/2' & circ.