

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED BY
MAY 25 1984
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator McKay Oil Corporation	8. Farm or Lease Name McKay-Berrendo
3. Address of Operator P. O. Box 2014, Roswell, New Mexico, 88202-2014	9. Well No. #1
4. Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660' FEET FROM East LINE, SECTION 2 TOWNSHIP 10S RANGE 24E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat - Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3554' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug and abandon well as follows:

Spot cmt plug from 200' to 100'. RIH w/8-5/8" 24# csg to 42'.
Perf csg from bottom up to 18'. Dump 56 yards of 1/2" gravel.
Fill hole w/Redi-mix cmt.

(Verbal approval per conversation between Jim Johnson of Horizon Drlg and Les Clements of OCC, Artesia, NM on 5-22-84).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie A. Clements TITLE Production Analyst DATE 5-22-84

APPROVED BY _____ TITLE Original Signed By
Leslie A. Clements
Supervisor District II DATE MAY 28 1984

CONDITIONS OF APPROVAL, IF ANY: