

RECEIVED BY BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
(Use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☒ OTHER ☐ **Plug & Abandoned**

2. NAME OF OPERATOR
McKay Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 2014 Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FWL & 1980' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GR 3623

5. LEASE DESIGNATION AND SERIAL NO. **ckf**
NM-26679

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
McKay Sundance Federal

9. WELL NO.
#1

10. FIELD AND POOL, OR WILDCAT
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 24, T-11-S, R-26-E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) Notice of intent to P & A

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We intend to P & A the above-captioned well

8 SK Cap from 6277' to ^{6177'} ~~6227'~~

8 SK Plug from 6033' to 5925' Tag Plug

22 SK Plug from 5150' to 5050'

60 SK Plug from 3650' to 3550'

45 SK Plug from 1346' to 1246' Tag Plug

30 SK Plug from 431' to 331'

15 SK Cap from 50' to Surface

← cut & pull 4 1/2" casing from 5100'



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Production Coordinator


DATE 10-18-85

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side