

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-005-62160
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	Lease Name or Unit Agreement Name LYNX
Name of Operator N. DALE NICHOLS	Well No. 1
Address of Operator P.O. BOX 1972, MIDLAND, TEXAS 79702	Pool name or Wildcat UND. FUSSLEMAN
Well Location Unit Letter <u>G</u> : <u>1815</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>19</u> Township <u>8S</u> Range <u>29E</u> NMPM <u>CHAVES</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3949 GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) 5-20-93 ATT.. TO PULL TUBING (UNSET PACKER BY PULLING UP). PULL 42000# 11000# OVER TUBING WEIGHT. WOULD NOT WORK FREE. PULL 48000# CAME LOSE. PULL TUBING AND FOUND THAT WE LEFT 13 JTS TUBING 1 GAS LIFT VALVE AND A PACKER IN THE WELL.
- 2) 5-21-93 TIH WITH TUBING SCREW BACK ON COLLAR PUMP WATER DOWN TUBING TO TRY TO HELP GET PACKER LOSE. PULL 45000# CAME LOSE. PULL TUBING DID NOT GET FISH.
- 3) 5-24-93 TIH WITH OVERSHOT AND HYD JARS. JARS SET TO WORK AT 35000# CAUGHT FISH AND JARRED SEVERAL TIMES TILL JARS GOT HOT AND QUIT WORKING. RELEASE OVERSHOT AND PULL TUBING.
- 4) TA WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 

TITLE BOOKKEEPER

DATE 12-06-2001

TYPE OR PRINT NAME JOHN E. NICHOLS

TELEPHONE NO. 915-697-1576

(This space for State Use)

APPROVED BY 

TITLE 

DATE 12-17-01

CONDITIONS OF APPROVAL, IF ANY:

