

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OCT - 1 1993

WELL API NO.
30-005-62176

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
L-6773

7. Lease Name or Unit Agreement Name

EASTLAND STATE

8. Well No.
3

9. Pool name or Wildcat
FOOR RANCH PRE-PERMIAN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
THE EASTLAND OIL COMPANY

3. Address of Operator
P. O. DRAWER 3488, MIDLAND TX 79702

4. Well Location
Unit Letter J : 1650 Feet From The SOUTH Line and 1980 Feet From The EAST Line
Section 13 Township 9-S Range 26E NMPM CHAVES County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull 2-3/8" tbg. Run 5 1/2" CIBP & set @5162'. Cap w/35' cmt.
2. RIII w/tbg. Load casing w/MLF (25# gel per Bbl. 9.5# Brine). Press. test csg. to 500#.
- * 3. POOH w/tbg.
4. PU on 5 1/2" & find free point. Est. @3300', cut & pull csg @free pt.
5. Spot 100' cement plug (50' in & 50' outside 5 1/2" stub.) Tag plug.
- * 6. Spot 100' " " from 1084'-984' (50' outside & 50' inside 8-5/8" shoe). Tag plug.
7. Install dry hole marker.
8. Clean location.

Plug 4488-4588

Plug Shoe 984-1240 Tag

Notify N.M.O.C.C. in sufficient time to witness

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed

TITLE PRODUCTION SUPERINTENDENT DATE 9/28/93

TYPE OR PRINT NAME TRAVIS REED

TELEPHONE NO. 915/683-6293

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: