



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

3/13/2002

Hi-Mountain Energy Corp.
PO Box 110
Midland, TX 79702

RE: O'Brien P #1 C-28-8-29 (30-005-62192)

Dear Sir:

On 03/06/02 a Mechanical Integrity Test was performed on the well indicated above.

It was found at that time that no bradenhead connection was visible. A search of the well file indicates the following:

1. 8 5/8 surface casing set at 336' and cemented to surface.
2. 4 1/2 production casing was set at 3005' and cemented with 200 sacks of Class A cement.

Since the production casing was not cemented to surface it is requested a valve be installed on the 4 1/2 annulus in order to monitor the area behind the production casing. This valve should be plumbed to the surface with a valve above ground to facilitate setting a guage for monitoring if necessary.

It is necessary that this work be accomplished on or before **04/15/02** and this office notified so that an inspection may be made.

Sincerely,

Gerry Guye
Compliance Officer
Oil Conservation Division, DistrictII

File