I N S	C L A	F A C	н 0 U	Q U A	NEW MEXICO OIL CONSERVATION (MMISSION FIELD TRIP REPORT		
P E	S S	IL	R S	R	Name B. W. Weaver	Date / -/585	308 Miles <u>Jar</u> District <u>II</u>
C T I	I F I C	I T Y	-	E R	Time of Departure7.e.	Time of Return	Miles <u>Jest</u> District <u>11</u> <u>7:00 Pm</u> Car No. <u>650</u> <u>3355</u>
O N	A T I N	_		H O U R S	In the space below indicate performed, listing wells or Signature	the purpose of the trip a	nd the dution
P	0	0	12		I Well K-	23-3-79 hot.	Petcorp Alpha AAA #1
						v	
	Set CIBPE 7800 Ft 35 Ft Cement ON Tup Set 2 C 7250 With 35 Ft Cement ON Top Cut 5/2 Casin Will Pull 5/2 and Lay down Temorrow						
						0	
					tule 5 h and	Lay down lemorre	
Cut 5/2 @ 3182 and Publied 1-17-85					-17-85		
	Set. 255× Class C (6338						
	Set 355X 11 @ 5550 to 5300 Set 50 5X 11 4% (C @ 3232 and Tage 3034						
					C. 3034		
				Set 50 5X 11 1, @ 2396 and Tag @ 2270			
		Set 355× 11 (422-322					
	Sut 15-3× 11 C Surface Finish 1.				15h 1-18-85		
				ļ		······································	
					<u>Mileage</u> UIC	Per Diem	Hours
					RFA	Other	
L	TYPE INSPECTION INSPECTION NATURE OF						
F C T F F F	- H - P - P - W - W - W		ecpiu ng ng C est /Worl 100 or 1	leanu kover Spill	related to injection pro- resulting from injection injection and production tests, surface injection R = Inspections relating to tion O = Other - Inspections not Reclamation Fund	related to injection or The	operations S = SWD U = Underground Storage G = General Operation F = Facility or location
E = indicates some form of unforcement action taken in the M = Meeting field (show immediately below the letter U, R or O) O = Other							