

(November 1983)
(Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Drawer DD

NUMBER 8

RECEIVED

August 31, 1985

WELL DESIGNATION AND SERIAL NO.

NM-23756

SUNDRY NOTICES AND REPORTS ON WELLS

MAY 29 1986

INDIAN, ALLOTTEE OR TRIBE NAME

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

O. C. D.

ARTESIA, OFFICE

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		8. FARM OR LEASE NAME West McKay-Harvey Fed	
2. NAME OF OPERATOR McKay Oil Corporation		9. WELL NO. 1	
3. ADDRESS OF OPERATOR P. O. Box 2014, Roswell, NM 88201		10. FIELD AND POOL, OR WILDCAT Wildcat W. Pool	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 660' FWL		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 17-8S-23E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4136' GR	12. COUNTY OR PARISH Chaves	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-5-86: TD 3566', PBTD 3514', perfed 3354-58' w/9 0.38" jts., spotted acid, treated w/500 gals. 7½% Abo acid. Set wireline plug in F nipple @ 3281', released from pkr.

3-6-86: Temp. PBTD 3279', perfed 2936, 45, 46, 47, 52, 58½, 66, 67, 3009, 3010 & 3028½ w/11 0.38" jets. Spotted acid, treated w/1500 gals. 7½% Abo acid. Fraced down 4½" csg. w/60,000 gals. 30# XL gel w/74,000# 20/40 and 20,000# 12/20 sd.

3-7-86: RIH w/ret. tool for pkr., unset pkr., POH & release pkr. RIH w/102 jts. 2 3/8" tbg. w/SN., set @ 2905'.

18. I hereby certify that the foregoing is true and correct

SIGNED Shaun Hamilton TITLE Agent DATE 3-11-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER

MAR 13 1986

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

