

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|-------------------------------------|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | <input checked="" type="checkbox"/> |
| FILE | <input checked="" type="checkbox"/> |
| U.S.G.S. | |
| LAND OFFICE | <input checked="" type="checkbox"/> |
| OPERATOR | <input checked="" type="checkbox"/> |

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS


(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. Name of Operator
STEVENS OPERATING CORPORATION

2. Address of Operator
P.O. Box 2408, Roswell, NM 88201

3. Location of Well



7. Unit Agreement Name

8. Farm or Lease Name
O'Brien "LLL"

9. Well No.
2

10. Field and Pool, or WHdcat
San Red Lake Ridge Andre

UNIT LETTER **K** **1980** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **21** TOWNSHIP **8S** RANGE **29E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3944' GR

12. County
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-24-87 Trip out w/ 112 rods & tbg, run & set CIBP @ 2800'.

7-27-87 Circ hole w/ salt mud, mix 5 sxs cmt cap @ 2730' - 2772'. Trip tbg out, Free Point & cut 5 1/2", 14# csg @ 1863', pull out 44 jts, ran tbg to 1921'. Mix 25 sxs cmt cap & cut off.

7-28-87 Tag top cmt @ 1803'. Pull up, set tbg @ 464'. Cmt w/ 25 sxs, WOC 3 hrs., Tag @ 290'. Set 20 surf plug.

INSTALL DRY HOLE MARKER

Post ID-2
8-28-87
PKA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John E. White TITLE Production Manager DATE 8/11/87

APPROVED BY Danell Moore TITLE Geologist DATE 4/7/88

CONDITIONS OF APPROVAL, IF ANY: