STATE OF NEW MEXICO THERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION ue. er corice heccives Form C-103 P. O. BOX 2088 DISTRIBUTION Revised 10-1-78 SANTA FE, NEW MEXICO 87501 SANTA FE 5a. Indicate Type of Lease FILE RECEIVED BY State X U.S.G.S. LAND OFFICE 5. State Oil & Gas Lease No. JUL 28 1987 OPERATOR SUNDRY NOTICES AND REPORTS ON WELLSO. C. D. 7. Unit Agreement Name OIL X OTHER-8. Farm or Lease Name riame of Operator Huber State STEVENS OPERATING CORPORATION 9. Well No. Address of Operator P.O. Box 2408, Roswell, NM 88201 10. Field and Pool, or Wildcat Location of Well 1980 660 FEET FROM THE South LINE AND THE West LINE, SECTION 16 TOWNSHIP 85 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Chaves 3969 GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PI UG AND ABANDON SCAFORM REMEDIAL WORK MPORABILY ABANDON CASING TEST AND CEMENT JOB CHANGE PLANS BLL OR ALTER CASING . Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Set CIBP @ 2850'. Load hole w/ salt mud. Ran 90 jts 7-13-87 2 3/8" tbq. Pmp 40' cmt cap. Prep to Free Point. Free Point @ 1898', cut csg & pull 65 jts . Ran 61 7-14-87 jts 2 3/8" tbg abd cmt w/ 25 sxs from 1848' to 1937. Tag cmt @ 1834'. Ran 13 jts 2 3/8 tbg set @ 409'. 7-15-87 Pmp 25 sxs cmt plug, tag cmt @ 320'. Place 30' surf pluq. INSTALL DRY HOLE MARKER in. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Production Manager

STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION --form C-103 -DISTRIBUTION P. O. BOX 2088 Revised 10-1-78 BANTA FE SANTA FE, NEW MEXICO 87501 FILE 5a. Indicate Type of Lease U.S.G.S. State X LAND OFFICE 5. State Oil & Gas Lease No. MUL 28 1987 OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS TO A DELEGE THIS FORM FOR PROPOSALS TO OBJECT ON TO DEEPEN OR PLUG BACK TO A DUSE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSA 7. Unit Agreement Name WELL X WELL OTHER-8. Farm or Lease Name . Name of Operator STEVENS OPERATING CORPORATION Huber State 9. Well No. 3. Address of Operator P.O. Box 2408, Roswell, NM 88201 10. Field and Pool, or Wildcat c. Location of Well SAN 1980 FEET FROM THE South Red Lake Ridge - ANDRI 660 29E LINE, SECTION ____16 8S 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3969 GR Chaves Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING FORM REMEDIAL WORK REMEDIAL WORK COMMENCE DRILLING OPHS. PLUG AND ABANDONMEN MPORARIET ABANDON CASING TEST AND CEMENT JOB CHANGE PLANS PULL OR ALTER CASING 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Set CIBP @ 2850'. Load hole w/ salt mud. Ran 90 jts 7-13-87 2 3/8" tbq. Pmp 40' amt cap. Prep to Free Point. Free Point @ 1898', cut csg & pull 65 jts . Ran 61 7-14-87 its 2 3/8" tbg abd cmt w/ 25 sxs from 1848' to 1937. Tag cmt @ 1834'. Ran 13 jts 2 3/8 tbg set @ 409'. 7-15-87 Pmp 25 sxs cmt plug, tag cmt @ 320'. Place 30' surf pluq. INSTALL DRY HOLE MARKER 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Production Manager 7-27-87

STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION ---Form C-103 -P. O. BOX 2088 DISTRIBUTION Revised 10-1-78 SANTA FE SANTA FE, NEW MEXICO 87501 FILE RECEIVED BY 5a, Indicate Type of Lease U.S.G.S. State X LAND OFFICE JUL 28 1987 5. State Oil & Gas Lease No. OPERATOR WELLS O. C. D. SUNDRY NOTICES AND REPORTS ON THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF PERMIT -" (FORM C-101) FOR ST 7, Unit Agreement Name WELL [WELL X OTHER. 8. Farm or Lease Name . Name of Operator Huber State STEVENS OPERATING CORPORATION 9. Well No. . Address of Operator #1 P.O. Box 2408, Roswell, NM 88201 10. Field and Pool, or Wildcat 4. Location of Well SAN FEET FROM THE South 1980 Red Lake Ridge -660 UNIT LETTER N 29E 8S 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Chaves 3969 GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: FORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDONMENT APORANIE ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING CHANGE PLANS 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Set CIBP @ 2850'. Load hole w/ salt mud. Ran 90 jts 7-13-87 2 3/8" tbg. Pmp 40' cmt cap. Prep to Free Point.

7-15-87 Tag cmt @ 1834'. Ran 13 jts 2 3/8 tbg set @ 409'.
Pmp 25 sxs cmt plug, tag cmt @ 320'. Place 30' surf plug.

Free Point @ 1898', cut csg & pull 65 jts . Ran 61

jts 2 3/8" tbg abd cmt w/ 25 sxs from 1848' to 1937.

	INSTALL DRY HOLE MARKER	
·		
16. I hereby certify that the information above is true and complete.	ete to the best of my knowledge and belief.	DATE 17-27-87
CONDITIONS OF APPROVAL, IF ANY		DATE 1

7-14-87

TNERGY AND MINERALS DEPARTMENT	OIL CONSERVATION DIVISION	Form C-103
DISTRIBUTION SANTA FE	P. O. BOX 2088	Revised 10-1-7
FILE	SANTA FE, NEW LEXISO 07501 RECEIVED BY	5a. Indicate Type of Lease
U.\$.o.\$.	WESTIATO BL	State X Fee
LAND OFFICE -	M III oo	5, State Otl & Gas Lease No.
OPERATOR	3UL 28 ₁₉₈₇	3, State Off & Gas Lease No.
SUNDRY NOTI	ICES AND REPORTS ON VELLS O. C. D.	
OIL X GAB OTHE		7. Unit Agreement Name
, Name of Operator		8. Form or Lease Name
STEVENS OPERATING CORPORA	TION	Huber State
P.O. Box 2408, Roswell, N	M 88201	#1
4. Location of Well		10. Field and Pool, or Wildcat SAN
UNIT LETTER N 660	FEET FROM THE South LINE AND 1980 FEET PR	™ Red Lake Ridge - ANDRES
	TOWNSHIP 8S RANGE 29E NMF	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3969 GR	Chaves (\\\\\\\\\\\
Check Appropring NOTICE OF INTENTI	riate Box To Indicate Nature of Notice, Report or CON TO:	Other Data NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING 1
TEMPORANIE ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER	
OTHER	D	
17. Describe Proposed or Completed Operations work) SEE RULE 1703.	(Clearly state all pertinent details, and give pertinent dates, include	ing estimated date of starting any proposed
7–13–87	Set CIBP @ 2850'. Load hole w/2 3/8" tbg. Pmp 40' cmt cap.	
7–14–87	Free Point @ 1898', cut csg & p jts 2 3/8" tbg abd cmt w/ 25 sx	
7-15-87	Tag cmt @ 1834'. Ran 13 jts 2 Pmp 25 sxs cmt plug, tag cmt @ plug.	3/8 tbg set @ 409'. 320'. Place 30' surf
	INSTALL DRY HOLE MARKER	
•		
16. I hereby certify that the information above is	true and complete to the best of my knowledge and belief.	
PLANTE LEWIS	Production Manager	DATE 17-27-87