

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87500-0288

Form C-103
Revised 10-1-7.

JUL 28 1987

O. C. D.

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
1. Name of Operator
STEVENS OPERATING CORPORATION
2. Address of Operator
P.O. Box 2408, Roswell, NM 88201
3. Location of Well
UNIT LETTER **N** **660** FEET FROM THE **South** LINE AND **1980** FEET FROM THE **West** LINE, SECTION **16** TOWNSHIP **8S** RANGE **29E** NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
Huber State
9. Well No.
#1
10. Field and Pool, or Wildcat **SAN Red Lake Ridge - ANDRES**
12. County
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)
3969 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-13-87 Set CIBP @ 2850'. Load hole w/ salt mud. Ran 90 jts 2 3/8" tbg. Pmp 40' cmt cap. Prep to Free Point.

7-14-87 Free Point @ 1898', cut csg & pull 65 jts. Ran 61 jts 2 3/8" tbg abd cmt w/ 25 sxs from 1848' to 1937.

7-15-87 Tag cmt @ 1834'. Ran 13 jts 2 3/8" tbg set @ 409'. Pmp 25 sxs cmt plug, tag cmt @ 320'. Place 30' surf plug.

INSTALL DRY HOLE MARKER

Post ID-2
8-14-87
P+A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John E. White* TITLE Production Manager DATE 7-27-87
APPROVED BY *Ralph Smith* TITLE *Ralph Smith* DATE 9-13-87
CONDITIONS OF APPROVAL, IF ANY: