Notember 1983).	CONS. COMMISSION FORMULATE Budget Bureau No. 1004. (DDer Instruct on ref Expires August 31, 1985
RECEIVED BY DEPARTM T OF THE INTERPORT BUREAU OF LAND MANAGEMENT	NM-57516
SEP 23 1950 NDRY NOTICES AND REPORTS ON (Do not use this form for proposals to drill or to deepen or plug back to Use "APPLICATION FOR PERMIT" for such proposals	WELLS
	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR DTHER Dry Hole	8. FARM OR LEASE NAME
	Smith Federal
3. The Eastland Oil Company	9. WELL NO.
P. () Drewer-3488 - Midland - Tr 79702	1
 P. Q. Drawer 3488 Midland. Tx 79702 Invition of Well (Report location clearly and in accordance with any State r See also space 17 below.) At surface 	equirements.* 10. FIELD AND POOL OF WILDCAT
	11. SEC., T., B., M., OR BLE. AND SUBVEY OR ABLE
1653'FNL, 2310'FEL (SW/4 NE/4) (Unit G)	Sec 22,T14S,R27E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, 3444' GR	etc.) 12. COUNTY OB PARIBH 13. STATE Chaves New Mexico
Check Appropriate box to indicate Nature of Notice, Keport, or Other Data	
	SUBSEQUENT REPORT OF :
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF REPAIRING WELL
PRACTUBE TREAT MULTIPLE COMPLETE SHOOT OB ACIDIZE ABANDON [®] XX	FRACTUBE TREATMENT ALTERING CABING
REFAIR WELL CHANGE PLANS	SHOOTING OR ACIDIZING ABANDONMENT*
(Other)	Norm: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and gones perti- nent to this work.)*	
Using a cable tool rig and Halliburton Services it is proposed to plug and abandon the Smith Federal No. 1. Casing in the hole is as follows: a. 10-3/4" surface casing at 104' w/100sx Class C and cemented to surface with 9 yards ready-mix. b. 8-5/8" protection string set at 242; and not cemented. c. 7" casing set at 707' and not cemented. 6" hole to T.D. of 728'.	
PLUGGING PROCEDURE AS FOLLOWS:	
1. Pull 7" casing and load hole w/9.6# mud using 2" tubing to T.D.	
2. Set plug from 728' to 628' w/35 sx in 6" and 8" hole thru 2" tbg.	
3. Pull 8" casing 4. Set plug from 154' to 54' w/50sx in 10" hole and 10-3/4" csg thru	
2" tbg. tag plug.	
 Set plug from 30' to surface w/15 sx in Set marker and proceed w/rehabilitation 	10-3/4" casing.
in the special Approval stipulations.	of the sufface as specified
Work is expected to begin about Sept 23, 1985.	
18. I hereby certify that the foregoing is true and correct	
SIGNED Cham Enviral TITLE Vice Dr	esident - Production DATE
(This space for Federal or State office use)	esident - filluction balk _ 9/11/05
· · ·	1
APPROVED BYAPPROVEDTITLE CONDITIONS OF APPROVAL IF ANESTER PETER W. CHESTER	DATE
SEP 20 1985	
Jee Instructions on Keverse Side	
Title 18 U.S.C. BUREAU OF LAND MANAGEMENT United States any fight with restance of the United States any fight statements or representations as to any matter within its jurisdiction.	