

5. LEASE DESIGNATION AND SERIAL NO.

NM 27185

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Ogle ADB Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

South Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit M, Sec. 31-T10S-R26E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

14. PERMIT NO.

API #30-005-62317

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3741' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☒

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☐

(Other)

☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

TD 4850'. Propose to plug and abandon well as follows:

Spot cement plug from 4250-4150' across Abo top.

Spot cement plug from 1935-1835' across Glorieta top.

Spot cement plug from 965-865' across 10-3/4" casing shoe. Tag this plug.

Set 50' plug at surface.

Verbal approval for the above plugging given by Mr. Peter Chester, BLM, Roswell, NM, on 4-9-86.

18. I hereby certify that the foregoing is true and correct

SIGNATURE *Peter Chester*

TITLE Production Supervisor

DATE

4-9-86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

APR 14 1986

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side