Started a 30' $12\frac{1}{4}$ " starter hole on	n 8–5–86.	
TEST WATER BEUT-OFF FRACTURE TREAT BHOOT OR ACIDIZE REPAIR WELL (Other) Spudding 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state proposed work. If well is directionally drilled, give sulnent to this work.)*	FRACTURE TRE SHOOTING OR (Other) (Note: Complet	ALTERING CABING ACIDIZING ABANDONMENT Report results of multiple completion on Wellton or Recompletion Report and Log form.)
Check Appropriate Box To	Indicate Nature of Notice,	Report, or Other Data BUBBEQUENT ERPORT OF:
14. PERMIT NO. 15. ELEVATIONS (She 4092)	ow whether DF, RT, GR, etc.) GL	12. COUNTY OB PARISH 18. STATE Chaves NM
599' FEL and 576' FSL		W. Pecos Slope Abo 11. BEC., T., B., M., OR BLK. AND BURYBY OR ARBA Sec. 24-6S-22E
Post Office Box 2014, Roswell, No. 1. Location or Well (Report location clearly and in accordant See also apace 17 below.) At aurface		#7 10. PIELD AND POOL, OR WILDCAT
OIL GAB WELL S OTHER 2. NAME OF OPERATOR McKay Oil Corporation	AUG -7 1986 O. C. D.	8. FARM OR LEADE NAME Remmele Fed
(I/o not use this form for proposals to drill or to dee Use "APPLICATION FOR PERMIT-	ben or that pack to a thickebt to	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND RE	PORTS ON WELLS	NM 36195 6. IF INDIAN, ALLOTTEE OR TRIBE I