DISTRICT I

Form C-103 Revised 1-1-89

CISF

OIL CONSERVATION DIVISIO

625 N. French Dr., Hobbs, NM 88240			1220 South St. F		WELL API NO.						
			Santa Fe, New N	/lexico 87505		30-005-6	2340				
DISTRICT II 11 S. First Street, A	urtesia, NM 882	10				5. Indicate Type of Lease	STATE		FEE	X	
OSTRICT III 000 Rio Brazos Rd	., Aztec, NM 87	410				6. State Oil & Gas Lease No.					
	SUN	- 4 is 3 is 3 is 3	Walter Fre								
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agree	ment Name				
. Type of Well: OIL WELL	GA WE	s LX	OTHER			O'B	rien				
Name of Operator				/		8. Well No.					
STRATA PRODUCTION COMPANY						#1					
. Address of Opera	tor					9. Pool Name or Wildcat					
	P.O. B	Miller Lake Abo									
l. Well Location Unit Letter	С	:660'	Feet From The North	Line and	1900'	Fee	t From The	W <u>e</u>	st	Line	
Section	25	Township	78	Range	29E	NMPM	Chav	es	Coun	ty	
			10. Elevation (Show wh	now whether DF, RKB, RT, GR, etc.)		1.3	10.0				
			4104'								
11.		Check A	ppropriate Box to Inc	dicate Nature of N	otice, Re	eport, or Other Data	a				
		OF INITENT	ONTO		_	UDOFOLIENT DE					

NOTICE	OF INTEN	TION TO:	SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING			
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT	x		
PULL OF ALTER CASING				CASING TEST AND CEMENT JOB					
OTHER:				OTHER:					
12. Describe Proposed or Completed Operations (Clearly state all partitions details, and give pertinent dates including estimated date of starting any proposed work)									

Notify OCD. MIRU. Dig & Line working pit. 4/29/02:

4/30/02: NUBOP & Flange. POOH w/tbg. RIH & set CIBP @ 6425'. Dump 35' cement on top.

RIH w/tbg & cir 10# @ mud @ 6380'. POOH & spot 25 sxs @ 2780'-2540'. POOH w/47

stands. Close in well.

POOH w/tbg. ND wellhead. Weld on pull nipple. Cut csg @ freepoint @ 3800'. Lay down 5/01/02:

2 its. Close in well.

POOH w/csg. RIH & spot 35 sxs @ 3850'. POOH. WOC. RIH & tag @ 3743'. 5/02/02:

POOH & spot 35 sxs @ 3550'. POOH w/25 stands. Close in well.

RIH & tag @ 3444'. POOH & spot 35 sxs @ 2378'. POOH. WOC. RIH & tag @ 2268'. 5/03/02:

POOH & spot 35 sxs @ 1283'. POOH. WOC. RIH & tag @ 1151'. POOH & spot 35 sxs @

977'. POOH. Close in well.

5/06/02: RIH @ tag @ 851'. POOH & spot 35 sxs @ 388'. POOH. WOC. RIH & tag @ 260'. POOH

& spot 15 sxs @ 60' to surface. RD. Move out. Install dry hole marker. Level pit & cellar.

I hereby certify that the info the best of my knowledge and belief.

TELEPHONE NO

(This space for State Use)

TYPE OR PRINT

APPROVED BY CONDITIONS OF APPROVAL



SEE RULE 1103

MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

STRATA PRODUCTION COMPANY

Lease: O'BRIEN # 1

Project: P & A – CEMENTING REPORT

04-30-2002 - SET CIBP @ 6425' - DUMP 35' CEMENT ON TOP

04-30-2002 - SPOT 25 SXS @ 2780'-2540'

05-02-2002 - SPOT 35 SXS @ 3850'- 3743' TAGGED - PULLED 3800' OF 5 1/2"

05-02-2002 - SPOT 35 SXS @ 3550'-3444' TAGGED

05-03-2002 - SPOT 35 SXS @ 2378'-2268' TAGGED

05-03-2002 - SPOT 35 SXS @1283'-1151' TAGGED

05-03-2002 - SPOT 35 SXS @ 977'-851' TAGGED

05-06-2002 - SPOT 35 SXS @ 388'- 260' TAGGED

05-06-2002 - SPOT 15 SXS @ 60' -SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10# MUD