STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT	
	Form C-103
DISTIGNUTION	Revised 10-1-78
REGENTA FE REGENTA FE. NEW MEXICO 87501	a, Indicate Type of Lease
	State X Fee
	5. State Oil & Gas Lease No.
OPERATOR .	
0. C. D.	LG 4336
SUNDRY NOTICE SAND REPORTS ON WELLS	
	7, Unit Agreement Name
DIL GAS X OTHER-	
	8, Farm or Lease Name
2. Name of Operator Yates Petroleum Corporation	Red Bluff State Unit
	9. Well No.
1. Address of Operator 105 South 4th St., Artesia, NM 88210	. 1
	10. Field and Pool, or Wildcat
4. Location of Well	Pecos Slope Abo
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM	
THE <u>East</u> Line, section <u>11</u> Township <u>75</u> Range <u>24E</u> NMPM.	
- Cliffic Internation (Show whether DF, RT, GR, etc.)	12. County
	Chaves Allilli
3970.4' GR	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	PLUG AND ABANDONMENT
PULL OR ALTER CASING	
OTHER	[]
OTHER	animated data of eventing any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed iverk) SEE RULE 1903.

Spudded 14-3/4" hole at 10:00 AM 10-29-86. Ran 24 jts 10-3/4" 40.5# J-55 casing, set 950'. 1-Texas Pattern Notched Guide shoe set 950', insert float set 914'. Cemented w/440 sx Pacesetter Lite w/5#/sx Hi-seal and 3% CaCl2. Tailed in w/150 sx Class "C" w/2% CaCl2. Compressive strength of cement - 1250 psi in 12 hrs. PD 3:00 PM 10-31-86. Bumped plug to 500 psi, released pressure and float held okay. Cement circulated 100 sx to pit. WOC. Drilled out 9:30 AM 11-1-86. WOC 18 hrs and 30 min. NU and tested to 1000 psi for 30 minutes, OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling. Lost circulation at 1312'. Set lost circulation plug at 1297' w/100 sacks Fixlite "C" w/12% Fix-add, 2% CaCl2, 5# Hi-seal and 1/4# celloseal. PD 3:45 AM 11-2-86. WOC. Fill hole. Set lost circulation plug at 1267' w/100 sacks Fixlite "C" w/12% Fix-add, 2% CaCl2, 5# Hi-seal, 1/4# celloseal. PD 8:00 AM 11-2-96. WOC. Drilled to 1419'. Set lost circulation plug at 1419' w/100 sacks Fixlite "C" w/12% Fix-add, 2% CaCl2, 5# Hi-seal and 1/4# celloseal. PD 2:30 AM 11-3-86. WOC. Fill hole. Set lost circulation plug at 1240' w/100 sacks Thixolite "C" with 12% Thixad, 2% CaCl2, 5#/sack Hi-seal, 3.5% ataclay and 1/2#/sack celloseal. PD 9:00 AM 11-3-86.

TOOH w/drill pipe. Shut down til location dries from rain.

18. I hereby certify that the inform	ation above is true and complete to the best of m	w knowledge and belief.		
sicher ( and ag	Dow allete TITLE Prod	luction Supervisor	BATE	6
	Original Signed By Mike Williams			5 <b>1986</b>
CONDITIONS OF APPROVAL, IF	Oil & Gas Inspector			