STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| PAH | INICI |
|-----|-------|
| | |
| | |
| 1 | |
| V | W |
| | |
| | |
| V | |
| | V |

CONDITIONS OF APPROVAL, IF ANYI

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 -

| FILE V. 1.0.6. | ZES SANTATE, NEW MEXICO STREPHINES | |
|--------------------------------------|--|------------------------------------|
| U.S.G.S. | SANTA FE, NEW MEXICO 87 RECEIVED | 5a. Indicate Type of Lease |
| | | State X Fee |
| LAND OFFICE | | 5. State Oil & Gas Lease No. |
| OPERATOR V | OCT 28 '87 | 1 |
| | | L 6408 |
| SUN | DRY NOTICES AND REPORTS ON WELLS Q.C.D. | |
| (DO NOT USE THIS FORM FOR USE "APPLI | PROPOSALS TO BRILL OF TO DELICE OF PROVIDER TO A DIFFERENT RESERVOIRS. | |
| | ARTESIA, OFFICE | 7. Unit Agreement Name |
| 01L GAB A | | |
| | OTHER- | 8. Form or Lease Name |
| Name of Operator | *11**** T / | l -, |
| rred Pool Di | illing, Inc. V | l |
| , Address of Operator | | 9, Well No. |
| P.O.Box 1393 | , Roswell, N.M.88201 | 2 |
| Location of Well | | 10. Field and Pool, or Wildcat |
| | courth 000 | MC SA |
| UNIT LETTER | 10 FEET FROM THE South LINE AND 990 FEET FROM | WC SA |
| | | |
| East Line, se | CTION 1 TOWNSHIP 9S RANGE 26E NMPM. | |
| | | |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | 3884' | Chaves |
| 6. | | |
| Chec | k Appropriate Box To Indicate Nature of Notice, Report or Oth | ier Data |
| NOTICE OF | INTENTION TO: SUBSEQUENT | REPORT OF: |
| • | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| Ħ | COMMENCE DRILLING OPHS. | PLUG AND ABANDONMENT |
| EMPORARILY ABANDON | | rese and assured in [|
| PULL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JOB | ŗ |
| • | OTHER P & A | |
| OTHER | | |
| | Operations (Clearly state all pertinent details, and give pertinent dates, including | |
| Oct. 20-87 | Spotted 25 sx Class C cement with 4% CaCl WOC 1.5hrs. Tagged plug at 2026'. Attempted to pump down 8 5/8 x 4½ annulus | |
| | 300#, could not pump down backside. Spotted 25 sx "C" neat cement at 1299'. Spotted 25 sx "C" neat cement at 831'. Spotted 25 sx "C" neat at 370'. Spotted 10 sx "C" neat at surface. Plug and abandon complete, intend to instaregulation dry hole marker. | |
| | Spotted 25 sx "C" neat cement at 1299'. Spotted 25 sx "C" neat cement at 831'. Spotted 25 sx "C" neat at 370'. Spotted 10 sx "C" neat at surface. Plug and abandon complete, intend to insta | |
| | Spotted 25 sx "C" neat cement at 1299'. Spotted 25 sx "C" neat at 370'. Spotted 25 sx "C" neat at 370'. Spotted 10 sx "C" neat at surface. Plug and abandon complete, intend to instaregulation dry hole marker. | 11 Part ID-2 10-14-88 P&A |
| | Spotted 25 sx "C" neat cement at 1299'. Spotted 25 sx "C" neat at 370'. Spotted 25 sx "C" neat at 370'. Spotted 10 sx "C" neat at surface. Plug and abandon complete, intend to instaregulation dry hole marker. | Part ID-2 10-14-88 P4A |