

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM
SUBMIT IN ORIGINALS (Other than original on reverse side)
LICATE

Budget Bureau No. 1004-0135
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO
NM-32322

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plug and abandon	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR McKay Oil Corporation	8. FARM OR LEASE NAME Miller Federal
3. ADDRESS OF OPERATOR Post Office Box 2014, Roswell, NM 88201	9. WELL NO. #4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FEL	10. FIELD AND POOL OR WILDCAT W. Pecos Slope Abo
14. PERMIT NO	11. SEC. T. B. M., OR BLK. AND SURVEY OR AREA Sec. 7-6S-23E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4203' GR	12. COUNTY OR PARISH Chaves
	13. STATE NM

RECEIVED

FEB 01 '88

O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Plug and abandon <input checked="" type="checkbox"/>	

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Operator plugged and abandoned well as follows

1. Blew well down day before and set sills for laying down tubing.
2. MIRU PU & BOP
3. Pulled tubing, tallied tubing out of hole
4. Ran tubing with CIBP to 2930', set CIBP. Loaded holw w/47 bbls. Tested CIBP to 500#.
5. RU and set 40 sxs. cement, plugged @ 2930'-2410' using 6 BW, flushed with 10 bbls. mud. Pulled up to 2410' (laid tubing down) pumped 20 bbls mud. Pulled up to 1160'.
6. Set 20 sxs. cement plug using 3 bbls water @ 1160'-910', flushed w/4 bbls mud. Pulled up to 910', displaced hole w/14 bbls mud.
7. Removed BOP
8. Pulled up to 100' (3 jts) set 10 sxs. cement plug using 1½ bbls. water.
9. Set dry hole marker. Rehabilitated surface of location and road as directed by BLM

Part ID-2
2-26-88
P & A

18. I hereby certify that the foregoing is true and correct

SIGNED Theresa Rodriguez TITLE Production Analyst DATE 12-24-87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____
Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
DATE
PETER W. CHESTER

JAN 11 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA