

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-62366

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG5565

7. Lease Name or Unit Agreement Name
Inexco State

8. Well No.
1

9. Pool name or Wildcat
Pecos Slope ABO (West)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ OTHER

2. Name of Operator
McKay Oil Corporation

3. Address of Operator
PO Box 2014, Roswell NM 88202-2014

4. Well Location
Unit Letter N : 1980 Feet From The West Line and 660 Feet From The South Line
Section 32 Township 5S Range 22E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4193 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/03/99 Notified OCD - Set CIBP @ 2878' - 5 sxs 2818' - Cir 9.5# Mud - 2 sxs LCM & Calc
3/04/99 POOH w/2140' of 4 1/2" CSG - Spot 25 sxs @ 2190' - 2065' tagged plug - spot 50 sxs
@ 1060' & 2 sxs LCM - No tag - Reset w/50 sxs @ 1060' - 2 sxs LCM + Calc on all plug
3/05/99 No tag @ 1060' - Reset plug spotting 50 sxs @ 1060' & 2 sxs LCM - No tag @ 1060' -
Reset w/ 50 sxs @ 1060' & 2 sxs LCM + Calc on all plugs
3/08/99 Tag plug @ 942' - Spot 30 sxs @ 100' to surface - Cut off wellhead - Installed
Dry Hole Marker

Location cleaned & ready for inspection

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tricia Moore TITLE Production Analyst DATE 01/10/2001

TYPE OR PRINT NAME Tricia Moore 505.623.4735 TELEPHONE NO.

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: