

☐ Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-005-62370

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG-5565

7. Lease Name or Unit Agreement Name:
INEXCO STATE

8. Well No.
5

9. Pool name or Wildcat
PECOS SLOPE ABO (WEST)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator
McKAY OIL CORPORATION

3. Address of Operator
PO BOX 2014, ROSWELL NM 88202-2014

4. Well Location
Unit Letter K : 1980 feet from the SOUTH line and 1980 feet from the WEST line
Section 33 Township 5S Range 22E NMPM CHAVES County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4113'GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

This well was plugged & abandoned in February 1999 as follows:

2/24/1999 Notify OCD. MIRU

2/25/1999 Kill well w/30 bbl Brine - set CIBP @ 2835' - load hole - cut csg @ 2070' - lay dwn 2 jts - SION.

2/26/1999 Lay dwn csg (50 jts) - RIH w/tbg & spot 25 sxs @ 2120' - POOH - WOC -tag plug @ 2018' - POOH & spot 50 sxs @ 964' - POOH - WOC - no tag - RIH w/tbg & spot 50 sxs @ 964' - POOH - SION.

3/01/1999 RIH & tag plug @ 852' - POOH & spot 30 sxs @ 100' to surface - cut off wellhead - install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tricia Moore TITLE PRODUCTION ANALYST DATE 12/13/2001

Type or print name TRICIA MOORE Telephone No. 505.623.4735
(This space for State use)

APPROVED BY [Signature] TITLE Wildcat Rep. P. DATE
Conditions of approval, if any:

Post Prod