

UNITED STATES **NM Oil and Gas Commission**
DEPARTMENT OF THE INTERIOR **(Other Lands Divisions on file)**
BUREAU OF LAND MANAGEMENT **Artesia, NM 88210**

Budget Chart No. 1004-1
Expires: Aug 1st 1, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-36194

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

McKay Oil Corporation ✓

JAN 26 '88

3. ADDRESS OF OPERATOR

Post Office Box 2014, Roswell, New Mexico 88201 O. C. D.

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
AT ROSWELL

610' FNL & 400' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

South Four Mile Draw Fed

9. WELL NO.

#6

10. FIELD AND FOOT OF WELL AT

W. Pecos Slope Abo

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 21-6S-22E

12. COUNTY OR PARISH, 13. STATE

Chaves

NM

14. PERMIT NO.

15. ELEVATION (Show whether IF RT, etc.)

4330' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF:

1. STOP WATER SHUT OFF

2. STOP PRODUCTION

3. FRACTURE TREATMENT

4. SHOOTING HOLES ETC.

5. SHOOTING HOLES

6. ABANDON

7. REPAIR CEMENT

8. PLUG BACK

9. OTHER

10. STOP PRODUCTION

11. FRACTURE TREATMENT

12. SHOOTING HOLES

13. OTHER

14. REPAIRING WELL

15. ALTERING CASING

16. ABANDONMENT

Plugged and abandoned


X

(Note: Report results of multiple completion on Well Completion or Re-completion Report and Log form.)

17. If well is plugged and abandoned, operator shall state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is plugged and abandoned, give subsurface location and measured and true vertical depths for all markers and zones pertinent to this work.

Operator plugged and abandoned well as follows:

1. Set CIBP @ 2869'
2. Set 20 sxs. cement plug @ 2869' - 2618'
3. Set 20 sxs. Cement plug @ 2049' - 1799'
4. Set 20 sxs. cement plug @ 1030' - 780'
5. Set 10 sxs. cement plug @ 100' - surface
6. Set Dry Hole Marker
7. Rehabilitate surface of location and road as directed by BLM.



Post ID-2
12-30-88
P+H

18. I hereby certify that the foregoing is true and correct

SIGNED Theresa Rodriguez

TITLE Production Analyst

DATE 1-5-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under well bond retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
PETER W. CHESTER

JAN 21 1988

